



February, 2026

***** IMPORTANT SAFETY RECALL REMINDER *****

According to our records, your 2025 Aviator has not had necessary safety recall repairs made. We urge you to have the free repair performed at your local dealership as soon as possible.

Recall Number and Description: **25C42 - Body Control Module C (BCMC) Inspection/Replacement**

What is the issue? On your vehicle, electronic components on the printed circuit board of the Body Control Module C (BCMC) may have been improperly soldered. As a result, when a trailer is connected to the vehicle and the vehicle's trailer tow electrical connector is utilized, the trailer's taillamps may not illuminate as intended. You may receive a trailer error message in your vehicle's instrument panel cluster when connecting a trailer. Additionally, you may experience inoperative power window/mirror switches or the vehicle's air conditioning system blowing warm air. You may also experience operability issues with your vehicle's DC/AC inverter, glove box light, vanity lights or dome lamps, alarm portion of the horn, rear defroster, USB chargers, and/or 12 V power points.

Inoperative trailer taillamps reduce visibility to other drivers, increasing the risk of a crash.

If you have questions or concerns, please contact our **Lincoln Recall Assistance Center (RAC) at 1-866-436-7332**. If you wish to contact us through the Internet, our address is: lincoln.com/support.

Thank you for your attention to this very important matter.

Febrero de, 2026

***** RECORDATORIO IMPORTANTE PROGRAMA DE SEGURIDAD *****

SegUR nuestros registros, no se realizaron en sur 2025 Aviator las reparaciones necesarias correspondientes a la campaña de seguridad. Le solicitamos que realice esta reparación gratuita en su distribuidor local lo antes posible.

Número y descripción de la campaña: **25C42 - Inspección/reemplazo del módulo de control de la carrocería C (BCMC)**

¿Cuál es el problema? Es posible que en su vehículo, algunos componentes electrónicos de la placa de circuito impreso del Módulo de control de la carrocería C (BCMC) se hayan soldado de manera incorrecta. Como consecuencia, al conectar un remolque al vehículo y utilizar el conector eléctrico de remolque del vehículo, las luces traseras del remolque podrían no encenderse de manera adecuada. Es posible que reciba un mensaje de error de remolque en el tablero de instrumentos de su vehículo al conectar un remolque. Asimismo, podría presentar errores en el funcionamiento de los interruptores de los controles de las ventanas eléctricas/espejos, o bien que el sistema de aire acondicionado del vehículo expulse aire caliente. También puede experimentar problemas de funcionamiento con el inversor de CC/CA de su vehículo, la luz de la guantera, las luces de cortesía o las luces de techo, la función de alarma de la bocina, el desempañador trasero, los cargadores USB y/o las tomas de corriente de 12 V. Las luces traseras del remolque que no funcionan reducen la visibilidad para otros conductores, lo que aumenta el riesgo de accidente.

Si tiene dudas o preguntas, comuníquese con nuestro **Centro de asistencia de campañas (RAC) Lincoln al 1-866-436-7332**. Si desea ponerse en contacto con nosotros a través de Internet, nuestra dirección es: lincoln.com/support.

Gracias por su atención en este asunto sumamente importante.

1 of 2
00000000000893 / 9 / 5



L I N C O L N

P.O. BOX 1904
DEARBORN, MI 48121-1904

Presorted STD
US Postage
PAID
R K C

0539357 A / 000000000000893 / 5



SEE OTHER SIDE FOR
OPENING INSTRUCTIONS

SEE OTHER SIDE FOR
OPENING INSTRUCTIONS

REMOVE THESE SIDE EDGES FIRST
THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION

REMOVE THESE SIDE EDGES FIRST
THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION

