



February, 2026

***** IMPORTANT SAFETY RECALL REMINDER *****

According to our records, your 2024 Mustang has not had necessary safety recall repairs made. We urge you to have the free repair performed at your local dealership as soon as possible.

Recall Number 25C43 - Body Control Module (BCM) Water Intrusion Inspection
and Description:

What is the issue? It is possible for water to enter your vehicle's Body Control Module (BCM), which may lead to corrosion and failure of the BCM.

Corrosion in the BCM causes loss of communication with exterior lighting components, and signal lamps that are required to be activated with low beams (front and rear side marker lamps, taillamps, and license plate lamps) are not activated. In addition, side markers and taillamps may flicker and not be steady burning.

If you have questions or concerns, please contact our **Ford Recall Assistance Center (RAC) at 1-866-436-7332**. If you wish to contact us through the Internet, our address is: ford.com/support.

Thank you for your attention to this very important matter.

Febrero de, 2026

***** RECORDATORIO IMPORTANTE PROGRAMA DE SEGURIDAD *****

SegUR nuestros registros, no se realizaron en sur 2024 Mustang las reparaciones necesarias correspondientes a la campaña de seguridad. Le solicitamos que realice esta reparación gratuita en su distribuidor local lo antes posible.

Número y descripción de la campaña: 25C43 - Inspección de ingreso de agua en el módulo de control de la carrocería (BCM)

¿Cuál es el problema? Es posible que entre agua en el módulo de control de la carrocería (BCM) de su vehículo, lo que puede provocar corrosión y fallas en el BCM.

La corrosión en el BCM provoca la pérdida de comunicación con los componentes de iluminación exterior y las luces direccionales que se deben activar con las luces bajas (luces de posición laterales delanteras y traseras, luces traseras y luz del portaplaca) no se activan. Además, la intrusión de agua en el BCM podría provocar que las funciones de las luces laterales de posición y de las luces traseras parpaddeen y no permanezcan encendidas de manera constante.

Si tiene dudas o preguntas, comuníquese con nuestro **Centro de asistencia de campañas (RAC) Ford al 1-866-436-7332**. Si desea ponerse en contacto con nosotros a través de Internet, nuestra dirección es: ford.com/support.

Gracias por su atención en este asunto sumamente importante.



P.O. BOX 1904
DEARBORN, MI 48121-1904

Presorted STD
US Postage
PAID
R K C

0000428 A / 000000000000909 / 32



SEE OTHER SIDE FOR
OPENING INSTRUCTIONS

SEE OTHER SIDE FOR
OPENING INSTRUCTIONS

REMOVE THESE SIDE EDGES FIRST
THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION

REMOVE THESE SIDE EDGES FIRST
THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION

