



February, 2026

***** IMPORTANT SAFETY RECALL REMINDER *****

According to our records, your 2024 Corsair has not had necessary safety recall repairs made. We urge you to have the free repair performed at your local dealership as soon as possible.

Recall Number and Description: **25C53 - Rear Combination Lamp Inspection/Replacement**

What is the issue? Your vehicle's left and/or right rear combination lamp (RCL) may have been damaged during vehicle assembly, which may allow water leakage into the lamp.
This may result in the left or right RCL becoming inoperative, affecting exterior lamp functions, including the backup lamp, stop lamp, taillamp, and/or rear turn signal lamp. Loss of these lighting functions reduces the vehicle's visibility and may not fully alert other drivers that the vehicle is braking, turning, or reversing, increasing the risk of a crash.

If you have questions or concerns, please contact our **Lincoln Recall Assistance Center (RAC) at 1-866-436-7332**. If you wish to contact us through the Internet, our address is: lincoln.com/support. Thank you for your attention to this very important matter.

Febrero de, 2026

***** RECORDATORIO IMPORTANTE PROGRAMA DE SEGURIDAD *****

SegUR nuestros registros, no se realizaron en sur 2024 Corsair las reparaciones necesarias correspondientes a la campaña de seguridad. Le solicitamos que realice esta reparación gratuita en su distribuidor local lo antes posible.

Número y descripción de la campaña: **25C53 - Inspección/reemplazo de la luz combinada trasera**

¿Cuál es el problema? Es posible que la luz trasera combinada (RCL) izquierda y/o derecha de su vehículo se haya dañado durante el ensamblaje del vehículo, lo que puede permitir la entrada de agua en la luz.
Esto podría provocar que la RCL izquierda o derecha no funcionen, lo cual afecta las funciones de las luces exteriores, incluidas las luces de retroceso, luces de freno, luces traseras y/o luces direccionales traseras. La pérdida de estas funciones de iluminación reduce la visibilidad del vehículo y podría que alertar completamente a otros conductores de que el vehículo está frenando, girando o retrocediendo, lo cual aumenta el riesgo de choque.

Si tiene dudas o preguntas, comuníquese con nuestro **Centro de asistencia de campañas (RAC) Lincoln al 1-866-436-7332**. Si desea ponerse en contacto con nosotros a través de Internet, nuestra dirección es: lincoln.com/support.

Gracias por su atención en este asunto sumamente importante.



L I N C O L N

P.O. BOX 1904
DEARBORN, MI 48121-1904

Presorted STD
US Postage
PAID
R K C

0539335 A / 000000000000925 / 16



SEE OTHER SIDE FOR
OPENING INSTRUCTIONS

SEE OTHER SIDE FOR
OPENING INSTRUCTIONS

REMOVE THESE SIDE EDGES FIRST
THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION

REMOVE THESE SIDE EDGES FIRST
THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION

