



February, 2026

**\*\*\* IMPORTANT SAFETY RECALL REMINDER \*\*\***

According to our records, your 2024 Nautilus has not had necessary safety recall repairs made. We urge you to have the free repair performed at your local dealership as soon as possible.

**Recall Number and Description:** 25SA2 - Pedestrian Alert System Software Update

**What is the issue?** Due to the quieter operation of hybrid vehicles at lower speeds, your vehicle's Pedestrian Alert System creates a specific sound to alert pedestrians to the vehicle's movement. On your vehicle, the pedestrian alert sound may not be generated in certain instances due to a Pedestrian Alert System fault in the Audio Control Module (ACM) and Digital Signal Processor (DSP), if equipped. If this occurs, a "Pedestrian Sounder Fault Service Now" warning message will appear on the Instrument Panel Cluster.

When a Pedestrian Alert System fault occurs, the vehicle will not emit pedestrian warning sounds and pedestrians may not hear an approaching vehicle, increasing the risk of injury to pedestrians.

If you have questions or concerns, please contact our **Lincoln Recall Assistance Center (RAC) at 1-866-436-7332**. If you wish to contact us through the Internet, our address is: [lincoln.com/support](http://lincoln.com/support).

Thank you for your attention to this very important matter.

Febrero de, 2026

**\*\*\* RECORDATORIO IMPORTANTE PROGRAMA DE SEGURIDAD \*\*\***

SegUR nuestros registros, no se realizaron en sur 2024 Nautilus las reparaciones necesarias correspondientes a la campaña de seguridad. Le solicitamos que realice esta reparación gratuita en su distribuidor local lo antes posible.

**Número y descripción de la campaña:** 25SA2 - Actualización de software del sistema de alerta del peatón

**¿Cuál es el problema?** Debido al funcionamiento más silencioso de los vehículos híbridos a velocidades más bajas, el sistema de alerta de peatón de su vehículo genera un sonido específico para alertar a los peatones sobre el movimiento del vehículo. En su vehículo, es posible que el sonido de alerta de peatón no se genere en ciertos casos debido a una falla del sistema de alerta de peatón en el módulo de control de audio (ACM) y el procesador de señales digitales (DSP), si está equipado. Si esto ocurre, aparecerá un mensaje de alerta "Falla en la alarma de peatón, requiere servicio inmediato" en el tablero de instrumentos.

Cuando ocurre una falla en el sistema de alerta de peatón, el vehículo no emite sonidos de alerta para peatones y estos podrían no escuchar un vehículo que se aproxima, lo que aumenta el riesgo de que los peatones sufran alguna lesión.

Si tiene dudas o preguntas, comuníquese con nuestro **Centro de asistencia de campañas (RAC) Lincoln al 1-866-436-7332**. Si desea ponerse en contacto con nosotros a través de Internet, nuestra dirección es: [lincoln.com/support](http://lincoln.com/support).

Gracias por su atención en este asunto sumamente importante.



L I N C O L N

P.O. BOX 1904  
DEARBORN, MI 48121-1904

Presorted STD  
US Postage  
**PAID**  
R K C

0014214 A / 000000000000960 / 6



SEE OTHER SIDE FOR  
OPENING INSTRUCTIONS

SEE OTHER SIDE FOR  
OPENING INSTRUCTIONS

REMOVE THESE SIDE EDGES FIRST  
THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION

REMOVE THESE SIDE EDGES FIRST  
THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION

