



Service Bulletin

American Honda Motor Co., Inc.

SAFETY RECALL

2024 XL750 Transalp • 2025 CMX1100 Rebel • 2025 CRF1100 Africa Twin • 2025 NT1100 SEALING BOLT OIL LEAK

NEW

(This bulletin has been revised to correct the affect models list and parts availability.)

BACKGROUND

Honda is launching a **SAFETY RECALL** on **CERTAIN 2024 XL750 Transalp, 2025 CMX1100 Rebel, 2025 CRF1100 Africa Twin, and 2025 NT1100 motorcycles** to replace the sealing bolt. Due to a manufacturing defect, the 22 mm sealing bolt was improperly machined, causing engine oil to leak past the bolt. If the motorcycle continues to operate with an oil leak, oil can splash onto the rear tire, resulting in a loss of traction and potentially increasing the risk of a crash or injury.

AFFECTED UNITS

As of May 27, 2025, you **MUST NOT SELL** any **AFFECTED NEW or USED** 2024 XL750 Transalp, 2025 CMX1100 Rebel, 2025 CRF1100 Africa Twin, and 2025 NT1100 motorcycles until it is repaired according to the upcoming Service Bulletin.

- To search for applicable recalls on a specific unit, you **MUST** use *Unit Information on iN*.
- To manage your affected new inventory, use your dealer *eResponsibility Report on iN*.

CUSTOMER NOTIFICATION

American Honda intends to mail customer letters to all owners of affected 2024 XL750 Transalp, 2025 CMX1100 Rebel, 2025 CRF1100 Africa Twin, and 2025 NT1100 motorcycles in July 2025. Customers will be informed that their motorcycle may be affected by a safety related defect and will be advised to make an appointment with an authorized Honda dealer for repair.

PARTS INFORMATION

Parts needed for the repair are expected to be available the week of July 21, 2025, and can be ordered according to the instructions in the forthcoming Service Bulletin. Dealers will be notified by an updated service bulletin should this parts availability date change.

NEW

SERVICE BULLETIN

Multiple Model Sealing Bolt #1, which includes all the information relating to this Safety Recall, is expected to be issued in late July 2025.

DEALER REPAIR RESPONSIBILITY

- Repairs must be performed by a qualified technician.
- Performing this repair exactly as shown in Repair Procedure instructions is critical for the remedy to be effective. Carefully follow all instructions.
- Service Management should inspect and confirm the repair.
- Dealer submission of a warranty claim affirms this repair was properly performed.