



Service Bulletin

American Honda Motor Co., Inc.

CRF1100 #4
September 2025

SAFETY RECALL

2020 ~ 2022, 2024, and 2025 CRF1100 AFRICA TWIN LEFT HANDLE SWITCH HARNESS

BACKGROUND

Honda is issuing a **SAFETY RECALL** on **CERTAIN 2020 ~ 2022, 2024, and 2025 CRF1100 Africa Twin** motorcycles to replace the left handle switch and wiring harness. Due to a manufacturing defect, the left handlebar switch harness can become damaged during normal use, potentially resulting in the complete or intermittent loss of horn function and/or the inability to switch the headlight from low beam to high beam.

If the horn does not function, a rider may be unable to warn other drivers of potentially hazardous situations, increasing the risk of a crash or injury. If the ability to switch from low beam to high beam is lost, the rider's visibility of the road, and visibility to other drivers, can be lost/reduced, increasing the risk of a crash or injury.

AFFECTED UNITS

As of September 2, 2025, you **MUST NOT SELL ANY NEW or USED 2020 ~ 2022, 2024, and 2025 CRF1100 AFRICA TWIN** motorcycles until it is repaired according to forthcoming Service Bulletin.

- To search for applicable recalls on a specific unit, you **MUST** use *Unit Information* on **iN**, available September 4, 2025.
- To manage your affected new inventory, use your dealer *eResponsibility Report* on **iN**, available September 5, 2025.

ALL left handle switch assemblies with a part number beginning with **35200-MKS** or **35200-MLN**

CUSTOMER NOTIFICATION

American Honda intends to mail customer letters to all owners of affected 2020 ~ 2022, 2024, and 2025 CRF1100 motorcycles in October 2025. The letter will inform customers that their motorcycle may be affected by a safety-related defect and, once parts become available, advise them to make an appointment with an authorized Honda dealer for repair.

PARTS INFORMATION

Repair parts are currently unavailable and are expected in January 2026. Dealers will be notified when parts become available by **iN** message and a revised service bulletin. If you have an in-service customer unit that may have a physically damaged left handle switch, contact TechLine for possible replacement options.

SERVICE BULLETIN

CRF1100 #4, which includes all parts and repair information relating to this Safety Recall, is expected to be issued in January 2026.

DEALER INVENTORY

American Honda is investigating options for flooring support due to the timing of repair parts availability. Look for a future **iN** message with revised service bulletin and additional details as they become available.

DEALER REPAIR RESPONSIBILITY

- Repairs must be performed by a qualified technician.
- Performing this repair exactly as shown in Repair Procedure instructions is critical for the remedy to be effective. Carefully follow all instructions.
- Service Management should inspect and confirm the repair.
- Dealer submission of a warranty claim affirms this repair was properly performed.

1 of 1