



Service Bulletin

American Honda Motor Co., Inc.

CBR600 #4
December 2025

SAFETY RECALL

2024-2026 CBR600RR/RA ENGINE OIL CONSUMPTION

BACKGROUND

Honda has issued a **STOP SALE NOTICE** on **CERTAIN 2024-2026 CBR600RR/RA** motorcycles due to an engine oil consumption concern. If the engine oil level is not checked frequently enough, the oil level may drop low enough to damage internal engine components. If the motorcycle continues to operate with a low engine oil level, the engine could seize, causing it to stall while riding and potentially increasing the risk of a crash or injury.

AFFECTED UNITS

As of December 12, 2025, you **MUST NOT SELL ANY NEW or USED** 2024-2026 CBR600RR/RA motorcycle until it is repaired according to forthcoming Service Bulletin.

- To search for applicable recalls on a specific unit, you **MUST** use *Unit Information on iN*, available December 16, 2025.
- To manage your affected new inventory, use your dealer *eResponsibility Report on iN*, available December 16, 2025.

CUSTOMER NOTIFICATION

American Honda intends to mail customer letters to all owners of affected motorcycles in February 2026. Customers will be informed that their motorcycle is affected by this safety-related defect and to make an appointment with an authorized Honda dealer to have their unit repaired.

SERVICE BULLETIN

This service bulletin (*CBR600 #4*) will be revised to include all parts and repair information related to this Safety Recall. Dealers will be notified by *iN* message.

DEALER REPAIR RESPONSIBILITY

- Repairs must be performed by a qualified technician.
- Performing this repair exactly as shown in Repair Procedure instructions is critical for the remedy to be effective. Carefully follow all instructions.
- Service Management should inspect and confirm the repair.
- Dealer submission of a warranty claim affirms this repair was properly performed.