



IC Bus, LLC  
2701 International Drive  
Lisle, IL 60532 USA

international.com

## IMPORTANT SAFETY RECALL 25514

NOVEMBER 2025

### INTERIM NOTICE

NHTSA RECALL NO. 25V-580

**THIS NOTICE APPLIES TO YOUR VEHICLE IDENTIFIED ON THE ENCLOSED CARD.**

Dear IC Bus Customer,

This notice is sent to you in accordance with the National Traffic and Motor Vehicle Safety Act.

IC Bus has decided that certain 2016 thru 2026 IC Bus™ CE series school buses built 01/15/2015 thru 05/29/2025 and 2016 thru 2022 IC Bus™ RE series school buses built 03/09/2015 thru 03/23/2021 with a side emergency door (feature codes 00047DCJ, 00047DCL, 47DCP, or 47DCT), luggage compartments, and dual riser seats fail to conform to Federal Motor Vehicle Safety Standard No. 210 - Seat Belt Assembly Anchorages and Federal Motor Vehicle Safety Standard No. 222 - School Bus Passenger Seating and Crash Protection.

### **REASON FOR THIS SAFETY RECALL**

The suspect vehicles do not conform to Federal Motor Vehicle Safety Standards (FMVSS):

No. 210, S4.2.2: The anchorages, attachment hardware, and attachment bolts for any of the following seat belt assemblies shall withstand a 13,345 N (3,000 pound) force applied to the lap belt portion of the seat belt assembly simultaneously with a 13,345 N (3,000 pound) force applied to the shoulder belt portion of the seat belt assembly, when tested in accordance with, at the choice of the manufacturer, S5.2.

No. 222, S5.1.4: Seat performance rearward. When a school bus passenger seat that has another seat behind it is subjected to the application of force as specified in S5.1.4.1 and S5.1.4.2.

### **RISK TO MOTOR VEHICLE SAFETY**

Noncompliance to FMVSS 210 S4.2.2 and 222 S5.1.4 may increase the passenger's risk of personal injury or death in the event of a crash.

### **ACTIONS YOU SHOULD TAKE**

If you are the lessor of this vehicle, please forward a copy of this notice to the lessee within ten days to comply with federal regulations.

If you do not own this vehicle, please fill out and return mail the enclosed card so that you will not be contacted again about this recall.

### **IF YOU NEED ASSISTANCE**

Refer to the Owner Assistance Guide section in your Owner's Manual or call toll free 1-800-448-7825.

IC Bus requests your prompt attention and patience regarding the correction of this defect and apologizes for any inconvenience this may cause you.

### **DEFECT REMEDY**

A final remedy has been determined. Parts are on order, but availability is currently unknown. A second notice will be sent to you, once the free remedy is available.