

H535 – LOSS OF REAR-VIEW CAMERA IMAGE

SAFETY RECALL



AFFECTED MODELS	19-20MY XE
VOLUME AFFECTED	5329 USA 143 CAN
REPAIR	A concern has been identified on certain vehicles, where the rear-view camera image display may become intermittent or permanently fail as a result of wiring damage in the trunk. A revised harness and overlay is required.
REPAIR TIME	1.2 hrs + DIDO
CAMPAIGN LAUNCH	The repair bulletin was published on TOPIx December 9th, 2025 .
NOTES	<p>Clients will receive a 2nd notification by mail requesting they now make a service appointment to complete the repair.</p> <p>NOTE: this Recall supersedes Recall H445</p> <p>Refer to Customer Service Parts Operations Bulletins 252612.020 - USA, JLRCS-2512.09 - CANADA published December 8th and 10th, 2025, for details of harnesses that have been pre-shipped to your retailer.</p>