

SAFETY RECALL N989 – SECOND ROW CENTRE SEAT BELT BUCKLE

SAFETY RECALL N989 – SECOND ROW CENTRE SEAT BELT BUCKLE	
AFFECTED MODEL	25MY Range Rover and Range Rover Sport
VOLUME AFFECTED	7276 USA 602 CAN
REPAIR	A concern has been identified where the row 2 seatbelt may not latch correctly into the center seat buckle. The seat belt buckle will need to be replaced
REPAIR TIME	0.3 hr + DIDO
CAMPAIGN LAUNCH	The vehicle quarantine notice was issued on March 7th, 2025, and the recall repair bulletin was published March 14th, 2025.
NOTES	Retailers are required to repair all affected vehicles in their control before sale and sold vehicles at the next service visit. Please refer to your respective regional Parts bulletins 242503.036 and JLRC25.03.011 for instructions on parts ordering.