

SAFETY RECALL N989 – ROW 2 CENTRE SEAT BELT BUCKLE

SAFETY RECALL N989 – ROW 2 CENTRE SEAT BELT BUCKLE	
AFFECTED MODEL	25MY Range Rover and Range Rover Sport
VOLUME AFFECTED	7276 USA 602 CAN
REPAIR	A potential concern has been identified where the row 2 seatbelt may not latch correctly into the center seat buckle. A replacement center seatbelt buckle will be required.
REPAIR TIME	0.3 hr + DIDO
CAMPAIGN LAUNCH	Vehicle Quarantine Notice was issued on March 7th, 2025. A Recall repair bulletin will be posted on TOPIx once a launch stock of parts arrive in market, expected w/c March 17 th , 2025.
NOTES	Retailers are required to Quarantine all affected vehicles that are within your control and refrain from releasing the vehicles for vehicle sale and delivery until the repair is completed. Current retailer inventory affected is 3191US and 375 CAN.