



Nissan North America, Inc.

One Nissan Way
Franklin, TN 37067

Mailing Address:
PO Box 685001
Franklin, TN 37068

August 26, 2025

Ms. Eileen Sullivan
Associate Administrator for Enforcement
National Highway Traffic Safety Administration
Attn: Recall Management Division (NVS-215)
Room W48-302
1200 New Jersey Avenue, SE
Washington, D.C. 20590

Dear Ms. Sullivan:

We are transmitting the enclosed second amendment to the Defect Information Report filed on June 26, 2025. This amendment updates section 7; Description of Corrective action.

Very truly,

A handwritten signature in black ink, appearing to read "Will Swindell".

Will Swindell
Manager,
Technical Compliance

Encl.

DEFECT INFORMATION REPORT

1. Manufacturer:

Cooperation Manufacturing Plant Aguascalientes (COMPAS)
Nissan North America, Inc., Canton Plant
Nissan North America, Inc., Smyrna Plant
Nissan Motor Kyushu Co., Ltd.

2. Vehicles Potentially Involved:

The production period of affected vehicles involved is shown in the table below.

<u>Model</u>	<u>Dates of Manufacture</u>	<u>Manufacturing Plant</u>
MY 2022 INFINITI QX55	February 10, 2021 to January 10, 2022	COMPAS
MY 2019 – 2022 INFINITI QX50	October 6, 2017 to January 10, 2022	COMPAS
MY 2019 – 2020 Nissan Altima	July 27, 2018 to November 27, 2019	Canton
MY 2019 – 2020 Nissan Altima	May 25, 2018 to December 11, 2019	Smyrna
MY 2022 – 2024 Nissan Rogue	November 22, 2021 to June 13, 2024	Smyrna
MY 2021 – 2024 Nissan Rogue	March 12, 2021 to August 1, 2024	Kyushu

This issue (as described in Section 5 below) is specific to vehicles equipped with either the 3-cylinder 1.5L (KR15DDT) or 4-cylinder 2.0L (KR20DDET) variable compression turbo (VC-Turbo) engine. Suspect engine assemblies have one-to-one traceability records linking the affected engine serial numbers to vehicles produced within the specified production periods for the models listed above. No other Nissan or INFINITI vehicles are affected.

The name, description and part number of the subject components are below:

<u>Part Name</u>	<u>Part Description</u>	<u>Part Number</u>
Engine - Bare	1.5L VC-Turbo 3-cylinder engine - Rogue (NNA, NML)	10102 4MUAA
Engine - Bare	1.5L VC-Turbo 3-cylinder engine - Rogue (NNA, NML)	10102 6RCAA
Engine - Bare	1.5L VC-Turbo 3-cylinder engine - Rogue (NNA)	10102 6RCAE
Engine - Bare	1.5L VC-Turbo 3-cylinder engine - Rogue (NNA)	10102 6RD0A
Engine - Bare	1.5L VC-Turbo 3-cylinder engine - Rogue (NNA)	10102 6RD1A
Engine - Bare	1.5L VC-Turbo 3-cylinder engine - Rogue (NNA)	10102 6RZ0A
Engine - Bare	2.0L VC-Turbo 4-cylinder engine - Altima, QX50, QX55 (NNA)	10102 5NA1A

3. Total Number of Vehicles Potentially Involved:

Approximately 443,899 vehicles may be affected as shown in the table below:

Model Year / Model	Number of Vehicles
MY 2022 INFINITI QX55	5,124
MY 2019 – 2022 INFINITI QX50	84,536
MY 2019 – 2020 Nissan Altima	5,685
MY 2021 – 2024 Nissan Rogue	348,554

4. Percentage of Vehicles Estimated to Actually Contain the Defect:

The defect is estimated to be present in 1.2% of vehicles equipped with the 3-cylinder 1.5L (KR15DDT) VC-Turbo engine and 0.8% of vehicles equipped with the 4-cylinder 2.0L (KR20DDET) VC-Turbo engine.

5. Description of the Defect:

Nissan has identified bearing failures in certain vehicles equipped with the subject 3-cylinder 1.5L or 4-cylinder 2.0L variable compression turbo engine (VC-Turbo) engines. A potential manufacturing defect in specific engine bearings (main, A-, C-, and L-link) or supporting engine components may cause engine damage and potentially lead to engine failure.

Bearing failures are not typically instantaneous and tend to progress over time, allowing drivers to receive multiple forms of audible and visible advance warnings, including abnormal noise from the engine compartment, rough running, malfunction indicator lights (MIL), and warning messages in the instrument cluster. If the engine fails while driving, it can result in a loss of motive power (LOMP), increasing the risk of a crash. In certain rare cases, a bearing failure may cause a breach in the engine block, allowing hot oil to be discharged, increasing the risk of an engine fire.

6. Chronology of Principal Events:

Chronology will be supplemented.

7. Description of Corrective Action:

Dealers received a preliminary announcement on July 2, 2025, were notified of the recall on July 15, 2025, and were updated on remedy status on August 15, 2025. Beginning August 25, 2025, owners of all potentially affected vehicles will be mailed an interim notification letter which will include instructions to contact a Nissan/INFINITI dealer if their vehicle is experiencing unusual engine noises, rough engine performance, illumination of the malfunction indicator light (MIL), or warning messages displayed in the instrument cluster. Nissan is finalizing the remedy and preparing parts for affected vehicles and anticipates the

final remedy and parts to be available in Q4 2025. This repair will be performed free of charge.

Nissan will include a statement in the Part 577 owner notification concerning reimbursement for the cost of obtaining a pre-notification remedy if the subject vehicles are no longer under warranty.

8. Copy of Notices:

Copies of all notices will be provided to NHTSA as they become available.