

H552/N945 – PASSENGER FRONTAL AIRBAG REPLACEMENT

SAFETY RECALL



AFFECTED MODELS	21-24MY E-PACE 20-25MY Range Rover Evoque
VOLUME AFFECTED	H552 - 1436 USA 95 CAN N945 - 21000 USA 3115 CAN
REPAIR	A concern has been identified on certain vehicles where during a passenger airbag deployment, the airbag may tear as a result of improper folding of the airbag during the airbag assembly process. A replacement passenger airbag will be required.
REPAIR TIME	1.1 hrs + DIDO
CAMPAIGN LAUNCH	Retailers were notified by Recall Admin Bulletins N945ADM1 and H552ADM1 (July 16th, 2025.) H552 (JAGUAR) repair was launched on November 28th, 2025 N945 (LAND ROVER) was launched Friday January 9th, 2026, and the bulletin republished as v2 January 26th, 2026, containing enhancements to the repair procedure.
NOTES	Retailers are required to hold all affected new vehicles in their inventory from sale until the repair is available and completed. Please refer to recall bulletin for instructions on used vehicles in retailer inventory. All affected VINs are flagged in TOPIx and the warranty portal. Owners previously notified via interim mailing are now being mailed a 2nd letter to inform them that the recall repair is now available and that they should contact their retailer to make a repair appointment. Initial quantities of RR Evoque parts were pre-shipped to retailers. Please refer to Parts Bulletin 252601.02 (US) and JLRCS-2601.02 (CAN) published January 8th, 2026, and January 13, 2026.