

D027 – RANGE ROVER (L405) FRONT SUSPENSION KNUCKLE CRACK – PHASE 3 SAFETY RECALL



AFFECTED MODELS	15-17MY Range Rover
VOLUME AFFECTED	37,961 US 3,343 CAN
REPAIR	A concern has been identified on certain Range Rover vehicles where the front suspension upper knuckle joint could develop a crack. In extreme cases where a crack in the front suspension knuckle has developed, this may lead to detachment of the upper suspension arm. Affected vehicles will require inspection for cracks and either the replacement of the suspension knuckle casting, or the addition of a supporting bracket.
REPAIR TIME	Between 0.8 and 1.9 hrs + DIDO
CAMPAIGN LAUNCH	<p>Retailer administration bulletin D027ADM1 was published on August 15th, 2025</p> <p>Given the recent significant increase in the affected population and increased parts demand repairs for Range Rover have been split into 3 phases.</p> <p>D027 is the 3rd phase with launch expected mid-April 2026 based on forecast parts supply lead times.</p> <p>Please review the content in the administration bulletin and observe all instructions relating to unsold vehicles in retailer inventory.</p> <p>Until these recall repairs are published, if a client presents a vehicle that is open in this recall and is diagnosed with a cracked knuckle, retailers should replace cracked knuckles using current parts. The repair should be submitted through the goodwill calculator and escalated for manual review.</p>
NOTES	