

N759 – RANGE ROVER (L405) FRONT SUSPENSION KNUCKLE CRACK – PHASE 1

SAFETY RECALL



AFFECTED MODELS	14-16MY Range Rover
VOLUME AFFECTED	10,018 US 549 CAN
REPAIR	A concern has been identified on certain Range Rover vehicles where the front suspension upper knuckle joint could develop a crack. A cracked front suspension knuckle may lead to detachment of the upper suspension arm. Affected vehicles will require both front steering knuckles to be inspected to identify at risk parts and where required a further inspection for cracks. Knuckles with cracks will be replaced and those without cracks require the addition of a supporting bracket.
REPAIR TIME	Between 0.1 and 1.7 hrs + DIDO
CAMPAIGN LAUNCH	Phase 1 - Launched on August 15 th , 2025. On November 14 th , 2025, the repair bulletin was updated to include an incremental knuckle inspection step to first ascertain if it is an at-risk part supplied by SAI, or a previous level of part from a different supplier, which is deemed not to pose a risk. Any not-at-risk parts do not require replacement or any supporting brackets installed.
NOTES	Owners were previously notified via interim mailing have now been mailed a 2nd letter to inform them that the recall repair is now available and that they should contact their retailer to make a repair appointment. All affected VIN are flagged in the warranty portal and TOPIx. BBSS reporting for affected vehicles in retailer inventory is not yet available