

D054 – TRANSMISSION CONTROL SWITCH MOISTURE INGRESS

SAFETY RECALL



AFFECTED MODELS	25MY RANGE ROVER , RANGE ROVER SPORT, DISCOVERY SPORT & 26MY RANGE ROVER EVOQUE
VOLUME AFFECTED	251 USA 28 CAN
REPAIR	A concern has been identified on certain vehicles as detailed above where it is possible that moisture has entered the Transmission Control Switch (TCS) during the assembly process. Under certain conditions there is a risk that this moisture may result in non-illumination of the Light Emitting Diode (LED) indicating the selected gear. Retailers are to replace the transmission control switch with an assured part
REPAIR TIME	Between 0.2 and 2.4hrs +DIDO
CAMPAIGN LAUNCH	Initial Quarantine instruction was issued October 8 th , 2025. The recall repair bulletin was published on TOPIx October 30 th , 2025
NOTES	Retailers are required to hold all affected new vehicles in their inventory from sale until the repair is completed. Sold vehicles should be repaired at the next service. Please refer to the warranty portal and TOPIx to confirm affected vehicles. BBSS reporting for affected vehicles in retailer inventory is not yet available Vehicles held in ports-of-entry will be repaired before wholesale.