

Toyota Motor North America, Inc.

Vehicle Safety & Compliance
Liaison Office
Mail Stop: W4-2D
6565 Headquarters Drive
Plano, TX 75024

February 10, 2026

AMENDED DEFECT INFORMATION REPORT (25V-869)

This amends Toyota's Part 573 Report of December 12, 2025, concerning the Hybrid Inverter Assembly on certain Toyota vehicles.

The Description of Corrective Repair Action is revised as noted below:

Description of Corrective Repair Action:

All known owners of the subject vehicles will be instructed to bring their vehicle to a dealership for an inspection of the hybrid inverter assembly bolt. Based on the inspection, either the hybrid inverter assembly bolt will be re-torqued to the correct specification or the inverter assembly will be replaced with an assembly containing a correctly torqued bolt. The remedy will be free of charge.