



U.S. Department of Transportation
**National Highway Traffic Safety
Administration**

**1200 New Jersey Avenue SE
Washington, DC 20590**

July 13, 2026

26V441

Martin Rapaport
BMW of North America, LLC
PO Box 1227
200 Chestnut Ridge Road
Westwood, NJ 07675-1227

Subject: Park Outside: Engine Starter May Corrode and Overheat

Dear Martin Rapaport:

This letter serves to acknowledge BMW of North America, LLC's notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

BMW/330E IPERFORMANCE/2016-2018
BMW/530E IPERFORMANCE/2018-2020
BMW/530E XDRIVE IPERFORMANCE/2018-2020
BMW/740LE XDRIVE IPERFORMANCE/2017-2019

Mfr's Report Date: July 08, 2026

NHTSA Campaign Number: 26V441

Components:

ELECTRICAL SYSTEM:STARTER ASSEMBLY:RELAY

Potential Number of Units Affected: 29,119

Problem Description:

BMW of North America, LLC (BMW) is recalling certain 2018-2020 530e xDrive, 2017-2019 740Le xDrive, 2018-2020 530e iPerformance, 2016-2018 330e iPerformance vehicles. The engine starter relay may corrode, causing the relay to overheat and short circuit.

Consequence:

A short circuit in the starter relay may increase the risk of a fire.

Remedy:



Owners are advised to park outside and away from structures until the remedy is complete. Dealers will replace the engine starter, free of charge. Owner notification letters are expected to be mailed August 28, 2026. Owners may contact BMW customer service at 1-800-525-7417. Vehicle Identification Numbers (VINs) involved in this recall will become searchable on NHTSA.gov beginning August 28, 2026.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-888-275-9171), or go to www.nhtsa.gov.

Please be reminded of the following requirements:

You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Please be reminded that under 49 U.S.C. § 30112(a)(3), it is illegal for a manufacturer, to sell, offer for sale, import, or introduce or deliver into interstate commerce, a motor vehicle or item of motor vehicle equipment that contains a safety defect once the manufacturer has notified NHTSA about that safety defect. This prohibition does not apply once the motor vehicle or motor vehicle equipment has been remedied according to the manufacturer's instructions.

As stated in 49 U.S.C. § 30118(f), submission of eight consecutive quarterly reports followed by three annual reports is required. As described in 573.7, submission of the first of eight consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter. The first of three consecutive annual status reports will be due on, or before, 1 year after the eighth quarterly report was submitted.

BMW of North America, LLC's contact for this recall will be DeMara Magruder who may be reached by email at demara.magruder@dot.gov. We look forward to working with you.

Sincerely,

Alex Ansley

Alex Ansley
Chief, Recall Management Division
Office of Defects Investigation
Enforcement