



U.S. Department of Transportation
**National Highway Traffic Safety
Administration**

**1200 New Jersey Avenue SE
Washington, DC 20590**

October 07, 2026

26V639

Cole Schreiber
Ring Power Corporation

Subject: Rear Bumper Hitch Plate May Bend

Dear Cole Schreiber:

This letter serves to acknowledge Ring Power Corporation's notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

TEREX/C4000/2020-2022
TEREX/C6000/2020-2021
TEREX/GENERAL 65/2020
TEREX/TC55/2020-2022

Mfr's Report Date: October 02, 2026

NHTSA Campaign Number: 26V639

Components:

TRAILER HITCHES

Potential Number of Units Affected: 100

Problem Description:

Ring Power Corporation (Ring Power) is recalling certain 2020 Terex General 65, 2020-2021 C6000, 2020-2022 C4000, and TC55 vehicles. The incorrect pintle hitch may have been installed without reinforced bracing, resulting in the rear bumper hitch plate bending.

Consequence:

The pintle hitch may fail, causing a loss of trailer control and increasing the risk of a crash.

Remedy:

Ring Power will inspect, replace the pintle hitch, and install bracing. Damaged bumpers will be replaced. All repairs will be performed free of charge. Owner notification letters are expected to be



mailed October 16, 2026. Owners may contact Ring Power's customer service at 904-613-0035. Ring Power's number for this recall is 23402.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-888-275-9171), or go to www.nhtsa.gov.

Please ensure the following requirements are met:

Reimbursement Plan Not Supplied

Provide a plan for reimbursing an owner or purchaser who incurred costs to obtain a remedy for the problem addressed by the recall within a reasonable time in advance of your company's notification of owners, purchasers, and dealers, in accordance with 49 CFR 573.13. Your company's plan may reference a general reimbursement plan previously submitted to NHTSA. A general reimbursement plan shall be updated every two years (49 CFR 573.13). If the vehicles are new and would be covered under the manufacturer's warranty program, please state that in the reimbursement section of an amended Part 573 Recall Report through the NHTSA Recalls Portal.

AMENDED 573 REQUIRED.

We have received your proposed owner notification letter and it is approved for distribution.

Please be reminded of the following requirements:

Copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Please be reminded that under 49 U.S.C. § 30112(a)(3), it is illegal for a manufacturer, to sell, offer for sale, import, or introduce or deliver into interstate commerce, a motor vehicle or item of motor vehicle equipment that contains a safety defect once the manufacturer has notified NHTSA about that safety defect. This prohibition does not apply once the motor vehicle or motor vehicle equipment has been remedied according to the manufacturer's instructions.

As stated in 49 U.S.C. § 30118(f), submission of eight consecutive quarterly reports followed by three annual reports is required. As described in 573.7, submission of the first of eight consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter. The first of three consecutive annual status reports will be due on, or before, 1 year after the eighth quarterly report was submitted.

Ring Power Corporation's contact for this recall will be Hensly Guerra who may be reached by email at hensly.guerra1@dot.gov. We look forward to working with you.

Sincerely,

Alex Ansley

Alex Ansley
Chief, Recall Management Division
Office of Defects Investigation
Enforcement