



U.S. Department
of Transportation

National Highway
Traffic Safety
Administration

Part 573 Safety Recall Report

26E042

Manufacturer Name: Prime-Time Specialty Vehicles

Submission Date: Jul 13, 2026

NHTSA Recall No.: 26E042

Manufacturer Recall No.: 26E022

Manufacturer Information

Population

Manufacturer Name: Prime-Time Specialty
Vehicles

Address: 56616 Elk Park Drive
Elkhart IN, 46516

Total number of potentially involved: 12

Estimated percentage with defect: 0.1%

Equipment Information

Brand / Trade 1: AMERICAN SEATING

Model: Q'STRAIT MAX

Part Number: Q-10007

Type: Original

Function: Securement

Size:

Production Dates: Nov 11, 2025 - Feb 17, 2026

Number of potentially involved: 12

Descriptive Information:

This recall is based off of the original equipment manufacturer whom is Q'Strait of Oakland Park, FL. We have purchased a limited amount of these kits and installed them into a limited amount of vehicles.

Defect / Noncompliance Description

Description of the defect or noncompliance:

Please reference IMPORTANT SAFETY RECALL: 26E022 from Q'Strait for further information. Our recall is duplicating the information given to us from the OE (Q'Strait).

The affected retractors may intermittently fail to auto-lock when a wheelchair is installed at a seating position equipped with an affected retractor.

FMVSS1:

FMVSS2:

Part 573 Safety Recall Report

26E042**Description of the safety risk, including crash, fire, death, injury:**

If this should occur, a wheelchair may be inadequately restrained, and the wheelchair occupant could be injured in the event of a crash.

Description of the cause:**Identification of any warning that can occur:**

Retractor not tightening.

Component Manufacturer

Tier of Supplier: Tier 1

Supplier Type: OEM

Name: Q'Straint

Address: 4031 NE 12th Terrace
Oakland Park FL, 33334

Country: United States

Involved Components

Component Name 1: QRT-360 Retractor

Component Description: Q011012 - PN QRT-360 - Model (PLI FITTING)

Component Part Number: Q-10007

Purchaser Information

The following manufacturers purchased this defective/noncompliant equipment for possible use or installation in new motor vehicles or new items of motor vehicle equipment:

Name: Prime Time Specialty Vehicles Inc

Address: 56616 Elk Park Drive
Elkhart IN, 46516

Country: United States

Chronology

Part 573 Safety Recall Report

26E042

Recall is processed under - specifically 49 CFR Part 573.3 (f):

(f) In the case of a defect or noncompliance decided to exist in original equipment installed in the vehicles of more than one manufacturer, compliance with § 573.6 is required of the equipment manufacturer as to the equipment item, and of each vehicle manufacturer as to the vehicles in which the equipment has been installed. Compliance with § 573.7 is required of the manufacturer who is conducting the recall campaign.

Events leading up to the decision are passed-thru from the OE.

Q'Straint delivered a written notice to Prime Time Specialty Vehicles Inc. in October 2025. This notice was to explain this recall. They have stated that they would need a list of potential customers that have purchased this product. We presented them a full list of potential end users. Q'Straint further explained that they would handle all filing and reporting on this recall on behalf of Prime Time Specialty Vehicles Inc. The recall notices we received we're also sent from Prime Time to respected bus dealerships as a friendly reminder. This was received and delivered out in October 2025.

In June of 2026, an agent of NHTSA reached out to management of Prime-Time. They were requesting for us to file a recall for this from Prime-Time. We posted this recall and explained that Q'Straint will be handling the recall reporting and notice to end users/customers.

Related NHTSA Recall Number: NHTSA Recall Campaign 26E022

Description of Remedy

Remedy Type: Replace

Consumer Advisories: ☐ Do Not Drive ☐ Park Outside

Description of remedy program:

Q'Straint will send out replacements free of charge.

How remedy component differs from recalled component:

See Q'Straint Campaign for all information under remedy section.

Not all the retractors shipped during this period contain this defect.

Identify how/when recall condition was corrected in production:

The affected retractors may intermittently fail to auto-lock when a wheelchair is installed at a seating position equipped with an affected retractor.

Reimbursement Plan

Description of reimbursement program:

Reimbursement and repair costs are handled through Q'Straint.

Part 573 Safety Recall Report

26E042**Period of reimbursement:****Costs to be reimbursed:****Address for reimbursement claims:**4031 NE 12th Terrace
Oakland Park FL, 33334

Recall Schedule

Description of recall schedule:

Recall schedule and reporting is handled by Q'Straint. Q'Straint is sending recall notices to owners and customers.

Planned Dealer Notification Date:☐ No Dealers**Planned Interim Owner Notification Date:**☒ No Owners**Planned Remedy Owner Notification Date:**☐ Phased Recall