



U.S. Department
of Transportation

National Highway
Traffic Safety
Administration

Part 573 Safety Recall Report

26E067

Manufacturer Name: Chrysler (FCA US, LLC)

Submission Date: Sep 29, 2026

NHTSA Recall No.: 26E067

Manufacturer Recall No.: 93D

Manufacturer Information

Population

Manufacturer Name: Chrysler (FCA US, LLC)

Address: 800 Chrysler Drive
CIMS 482-00-91
Auburn Hills MI, 48326-
2757

Total number of potentially involved: 8,378

Estimated percentage with defect: 7.7%

Equipment Information

Brand / Trade 1: MOPAR

Model: WIRING

Part Number: 68526700AB

Type:

Function / Version:

Size / Configuration:

Production Dates: Aug 02, 2021 - May 02, 2026

Number of potentially involved: 38

Descriptive Information:

Some left body harness assemblies may be susceptible to water intrusion leading to corrosion within the wiring harness.

The suspect part population includes left body harness assemblies built from August 2, 2021, through May 2, 2026, and was determined using supplier production records.

There are no similar left body harness assemblies not included in this recall.

Brand / Trade 2: MOPAR

Model: WIRING

Part Number: 68526701AB

Type:

Function / Version:

Size / Configuration:

Part 573 Safety Recall Report

26E067

Production Dates: Aug 02, 2021 - Jul 30, 2026

Number of potentially involved: 204

Descriptive Information:

Some left body harness assemblies may be susceptible to water intrusion leading to corrosion within the wiring harness.

The suspect part population includes left body harness assemblies built from August 2, 2021, through July 30, 2026, and was determined using supplier production records.

There are no similar left body harness assemblies not included in this recall.

Brand / Trade 3: MOPAR

Model: WIRING

Part Number: 68526702AB

Type:

Function / Version:

Size / Configuration:

Production Dates: Oct 30, 2021 - Aug 14, 2026

Number of potentially involved: 654

Descriptive Information:

Some left body harness assemblies may be susceptible to water intrusion leading to corrosion within the wiring harness.

The suspect part population includes left body harness assemblies built from October 30, 2021, through August 14, 2026, and was determined using supplier production records.

There are no similar left body harness assemblies not included in this recall.

Brand / Trade 4: MOPAR

Model: WIRING

Part Number: 68526703AB

Type:

Function / Version:

Size / Configuration:

Production Dates: Feb 07, 2022 - Jun 18, 2026

Number of potentially involved: 4

Descriptive Information:

Some left body harness assemblies may be susceptible to water intrusion leading to corrosion within the wiring harness.

Part 573 Safety Recall Report

26E067

The suspect part population includes left body harness assemblies built from February 7, 2022, through June 18, 2026, and was determined using supplier production records.

There are no similar left body harness assemblies not included in this recall.

Brand / Trade 5: MOPAR

Model: WIRING

Part Number: 68526705AB

Type:

Function / Version:

Size / Configuration:

Production Dates: Feb 07, 2022 - Jul 31, 2026

Number of potentially involved: 8

Descriptive Information:

Some left body harness assemblies may be susceptible to water intrusion leading to corrosion within the wiring harness.

The suspect part population includes left body harness assemblies built from February 7, 2022, through July 31, 2026, and was determined using supplier production records.

There are no similar left body harness assemblies not included in this recall.

Brand / Trade 6: MOPAR

Model: WIRING

Part Number: 68526707AB

Type:

Function / Version:

Size / Configuration:

Production Dates: Jan 19, 2022 - Aug 14, 2026

Number of potentially involved: 68

Descriptive Information:

Some left body harness assemblies may be susceptible to water intrusion leading to corrosion within the wiring harness.

The suspect part population includes left body harness assemblies built from January 19, 2022, through August 14, 2026, and was determined using supplier production records.

There are no similar left body harness assemblies not included in this recall.

Brand / Trade 7: MOPAR

Part 573 Safety Recall Report

26E067**Model:** WIRING**Part Number:** 68529722AB**Type:****Function / Version:****Size / Configuration:****Production Dates:** Jul 07, 2021 - Jul 30, 2025**Number of potentially involved:** 5,262**Descriptive Information:**

Some jumper harness assemblies may be susceptible to water intrusion leading to corrosion within the wiring harness.

The suspect part population includes jumper harness assemblies built from July 7, 2021, through July 30, 2025 when suspect jumper harnesses were no longer produced. The scope was determined using supplier production records.

There are no similar left body harness assemblies not included in this recall.

Brand / Trade 8: MOPAR**Model:** WIRING**Part Number:** 68586800AB**Type:****Function / Version:****Size / Configuration:****Production Dates:** Mar 18, 2022 - Feb 04, 2026**Number of potentially involved:** 47**Descriptive Information:**

Some left body harness assemblies may be susceptible to water intrusion leading to corrosion within the wiring harness.

The suspect part population includes left body harness assemblies built from March 18, 2022, through February 4, 2026, and was determined using supplier production records.

There are no similar left body harness assemblies not included in this recall.

Brand / Trade 9: MOPAR**Model:** WIRING**Part Number:** 68586801AB**Type:****Function / Version:**

Part 573 Safety Recall Report

26E067

Size / Configuration:

Production Dates: Mar 18, 2022 - May 13, 2026

Number of potentially involved: 561

Descriptive Information:

Some left body harness assemblies may be susceptible to water intrusion leading to corrosion within the wiring harness.

The suspect part population includes left body harness assemblies built from March 18, 2022, through May 13, 2026, and was determined using supplier production records.

There are no similar left body harness assemblies not included in this recall.

Brand / Trade 10: MOPAR

Model: WIRING

Part Number: 68586802AB

Type:

Function / Version:

Size / Configuration:

Production Dates: Mar 18, 2022 - Feb 25, 2026

Number of potentially involved: 1,226

Descriptive Information:

Some left body harness assemblies may be susceptible to water intrusion leading to corrosion within the wiring harness.

The suspect part population includes left body harness assemblies built from March 18, 2022, through February 25, 2026, and was determined using supplier production records.

There are no similar left body harness assemblies not included in this recall.

Brand / Trade 11: MOPAR

Model: WIRING

Part Number: 68586804AB

Type:

Function / Version:

Size / Configuration:

Production Dates: Aug 16, 2022 - Feb 26, 2026

Number of potentially involved: 15

Descriptive Information:

Some left body harness assemblies may be susceptible to water intrusion leading to corrosion within the wiring harness.

Part 573 Safety Recall Report

26E067

The suspect part population includes left body harness assemblies built from August 16, 2022, through February 26, 2026, and was determined using supplier production records.

There are no similar left body harness assemblies not included in this recall.

Brand / Trade 12: MOPAR

Model: WIRING

Part Number: 68586805AB

Type:

Function / Version:

Size / Configuration:

Production Dates: Sep 30, 2022 - Feb 06, 2026

Number of potentially involved: 11

Descriptive Information:

Some left body harness assemblies may be susceptible to water intrusion leading to corrosion within the wiring harness.

The suspect part population includes left body harness assemblies built from September 30, 2022, through February 6, 2026, and was determined using supplier production records.

There are no similar left body harness assemblies not included in this recall.

Brand / Trade 13: MOPAR

Model: WIRING

Part Number: 68610907AB

Type:

Function / Version:

Size / Configuration:

Production Dates: Aug 25, 2022 - Aug 05, 2025

Number of potentially involved: 4

Descriptive Information:

Some left body harness assemblies may be susceptible to water intrusion leading to corrosion within the wiring harness.

The suspect part population includes left body harness assemblies built from August 25, 2022, through August 5, 2025, and was determined using supplier production records.

There are no similar left body harness assemblies not included in this recall.

Brand / Trade 14: MOPAR

Part 573 Safety Recall Report

26E067

Model: WIRING

Part Number: 68628910AA

Type:

Function / Version:

Size / Configuration:

Production Dates: Nov 10, 2023 - Jan 26, 2026

Number of potentially involved: 3

Descriptive Information:

Some left body harness assemblies may be susceptible to water intrusion leading to corrosion within the wiring harness.

The suspect part population includes left body harness assemblies built from November 10, 2023, through January 26, 2026, and was determined using supplier production records.

There are no similar left body harness assemblies not included in this recall.

Brand / Trade 15: MOPAR

Model: WIRING

Part Number: 68628911AA

Type:

Function / Version:

Size / Configuration:

Production Dates: Aug 12, 2023 - Feb 16, 2026

Number of potentially involved: 4

Descriptive Information:

Some left body harness assemblies may be susceptible to water intrusion leading to corrosion within the wiring harness.

The suspect part population includes left body harness assemblies built from August 12, 2023, through February 16, 2026, and was determined using supplier production records.

There are no similar left body harness assemblies not included in this recall.

Brand / Trade 16: MOPAR

Model: WIRING

Part Number: 68628912AA

Type:

Function / Version:

Size / Configuration:

Part 573 Safety Recall Report

26E067

Production Dates: Feb 09, 2023 - Mar 27, 2026

Number of potentially involved: 13

Descriptive Information:

Some left body harness assemblies may be susceptible to water intrusion leading to corrosion within the wiring harness.

The suspect part population includes left body harness assemblies built from February 9, 2023, through March 27, 2026, and was determined using supplier production records.

There are no similar left body harness assemblies not included in this recall.

Brand / Trade 17: MOPAR

Model: WIRING

Part Number: 68628913AA

Type:

Function / Version:

Size / Configuration:

Production Dates: Mar 28, 2024 - May 12, 2025

Number of potentially involved: 1

Descriptive Information:

Some left body harness assemblies may be susceptible to water intrusion leading to corrosion within the wiring harness.

The suspect part population includes left body harness assemblies built from March 28, 2024, through May 12, 2025, and was determined using supplier production records.

There are no similar left body harness assemblies not included in this recall.

Brand / Trade 18: MOPAR

Model: WIRING

Part Number: 68586801AC

Type:

Function / Version:

Size / Configuration:

Production Dates: Feb 20, 2026 - Jun 10, 2026

Number of potentially involved: 63

Descriptive Information:

Some left body harness assemblies may be susceptible to water intrusion leading to corrosion within the wiring harness.

Part 573 Safety Recall Report

26E067

The suspect part population includes left body harness assemblies built from February 20, 2026, through June 10, 2026, and was determined using supplier production records.

There are no similar left body harness assemblies not included in this recall.

Brand / Trade 19: MOPAR

Model: WIRING

Part Number: 68586802AC

Type:

Function / Version:

Size / Configuration:

Production Dates: Feb 20, 2026 - Jun 26, 2026

Number of potentially involved: 192

Descriptive Information:

Some left body harness assemblies may be susceptible to water intrusion leading to corrosion within the wiring harness.

The suspect part population includes left body harness assemblies built from February 20, 2026, through June 26, 2026, and was determined using supplier production records.

There are no similar left body harness assemblies not included in this recall.

Defect / Noncompliance Description

Description of the defect or noncompliance:

Corroded wiring harnesses can cause intermittent or permanent loss of power steering assist which may result in an inconsistent steering effort.

FMVSS1:

FMVSS2:

Description of the safety risk, including crash, fire, death, injury:

Inconsistent steering effort can increase the risk of a crash.

Description of the cause:

Identification of any warning that can occur:

Part 573 Safety Recall Report

26E067

None prior to failure, however the Electric Power Steering ("EPS") fault warning light may illuminate when there is a loss of power steering assist.

Component Manufacturer

Tier of Supplier:

Supplier Type:

Name: See - Harness Supplier Information.pdf

Address:

Country:

Involved Components

Component Name 1: Body Harness / Jumper Harness

Component Description: Body Harness / Jumper Harness

Component Part Number: Please see attached supplement information titled FCA US LLC Recall Part Numbers 93D-09292026.pdf

Purchaser Information

The following manufacturers purchased this defective/noncompliant equipment for possible use or installation in new motor vehicles or new items of motor vehicle equipment:

Name:

Address:

Country:

Chronology

- On September 22, 2025, the National Highway Traffic Safety Administration ("NHTSA") sent FCA US LLC ("FCA US") a pre-investigation inquiry regarding nine complaints made to the NHTSA for loss or partial loss of power steering assist.
- On September 30, 2025, NHTSA sent FCA US one additional complaint made to the NHTSA regarding loss or partial loss of power steering assist.
- On October 16, 2025, FCA US provided its response to the NHTSA.

Part 573 Safety Recall Report

26E067

- On January 8, 2026, the FCA US Technical Safety and Regulatory Compliance ("TSRC") Product Investigation organization opened an internal investigation related to this issue.
- On March 2, 2026, NHTSA's Office of Defect Investigations opened Preliminary Evaluation PE26-002 into loss of power steering assist on 2022-2024 MY Ram ProMaster vehicles.
- Between March 2026 and June 2026, FCA US TSRC organization investigated loss or partial loss of power steering assist occurring in the subject vehicles due to water causing corrosion in the connectors, and into the steering gear directly.
- On June 9, 2026, NHTSA issued an Information Request related to PE26-002 and FCA US responded in full on July 24, 2026. FCA US identified during its investigation 437 customer assistance records, 2799 warranty claims and 191 field reports potentially relating to this issue for all markets with dates of receipt ranging from April 14, 2022 to June 9, 2026.
- From July 2026 through August 2026, the FCA US TSRC organization continued its internal investigation into some 2022-2026 MY Ram ProMaster 1500, 2500, 3500 and 3500 EV vehicles and met with FCA US Engineering and Manufacturing to review vehicle production records and design changes to the EPS system to understand potential root cause, customer consequence and vehicle scope.
- As of September 2, 2026, FCA US identified an additional 974 other reports potentially relating to this issue for all markets with dates of receipt ranging from April 12, 2022 to April 10, 2026.
- FCA US is aware of one accident but no injuries potentially related to this issue for all markets.
- On September 22, 2026, FCA US determined, through the Vehicle Regulations Committee, that a safety defect exists in certain motor vehicle equipment.

Related NHTSA Recall Number:

Description of Remedy

Remedy Type: Inspect, Replace, Repurchase

Consumer Advisories: ☐ Do Not Drive ☐ Park Outside

Description of remedy program:

FCA US LLC will conduct a voluntary safety recall to inspect and if necessary, replace the wiring harness and EPS gear if installed on a vehicle, or repurchase the wiring harness, if not installed on a vehicle.

How remedy component differs from recalled component:

Remedy wiring harnesses have improved sealing that prevents water intrusion.

Identify how/when recall condition was corrected in production:

Part 573 Safety Recall Report**26E067****Reimbursement Plan**

Manufacturer used general reimbursement plan on file.

Recall Schedule**Description of recall schedule:**

**09/29/2026: FCA US will notify dealers on or about 09/30/2026 and begin notifying owners on or about 11/17/2026.

Planned Dealer Notification Date: Sep 30, 2026 - Sep 30, 2026 ☐ No Dealers

Planned Interim Owner Notification Date: Nov 17, 2026 - Nov 17, 2026 ☐ No Owners

Planned Remedy Owner Notification Date: ☐ Phased Recall