



U.S. Department
of Transportation

National Highway
Traffic Safety
Administration

Part 573 Safety Recall Report

26V005

Manufacturer Name: Jaguar Land Rover North America, LLC

Submission Date: Jan 09, 2026

NHTSA Recall No.: 26V005

Manufacturer Recall No.: D082

Manufacturer Information

Population

Manufacturer Name: Jaguar Land Rover North America, LLC

Address: 100 Jaguar Land Rover Way
Mahwah NJ, 07495

Total number of potentially involved: 8

Estimated percentage with defect: 100%

Vehicle Information

Vehicle 1: 2026-2026 LAND ROVER RANGE ROVER SPORT

Product Category: Light Vehicles

Product Type: Multipurpose Passenger Vehicle

Fuel / Propulsion: Spark Ignition Fuel

Production Dates: Nov 04, 2025 - Nov 05, 2025

Number of potentially involved: 8

Descriptive Information:

2026 Land Rover Range Rover Sport in the selected VIN range.

The population of vehicles was determined through inspection of build records and comparison to as-certified vehicle data, where an update notice had been incorrectly marked as completed in the port of entry ahead of vehicle release.

Defect / Noncompliance Description

Description of the defect or noncompliance:

A concern has been identified where a small number of 26MY Range Rover Sport 6-cylinder petrol engine vehicles have been built with weight information on the certification label which exceeds that certified by 200 lbs.

FMVSS1:

FMVSS2:

Description of the safety risk, including crash, fire, death, injury:

Part 573 Safety Recall Report

26V005

Incorrect weight information on the certification label could lead to customers overloading the vehicles, increasing the risk of a crash.

Description of the cause:

Identification of any warning that can occur:

Component Manufacturer

Tier of Supplier: Tier 1

Supplier Type: OEM

Name: Jaguar Land Rover Limited

Address: Abby Road
Whitley
Coventry Foreign States, CV3 4LF

Country: United Kingdom

Involved Components

Component Name 1: Certification Label

Component Description: Certification Label

Component Part Number: S9X2-1532-GB

Component Name 2: Certification Label

Component Description: Certification Label

Component Part Number: S9X2-1532-HB

Chronology

On 10 November 2025, following information being received from the vehicle assembly plant suggesting that incorrect information may have been printed on the certification label, a Vehicle Assembly Plant pre stop shipment meeting was held. The vehicle build records were reviewed and it was concluded that a number of vehicles were affected by this condition. It was established that all the affected vehicles were still in JLR control and therefore an Update Prior to Sale Notice (UPS) was issued to remedy vehicles prior to entry into commerce. On 11 November 2025 the matter was first reviewed in JLR's Product Safety and Compliance Committee (PSCC), and it was agreed that the status of the UPS would be

Part 573 Safety Recall Report

26V005

regularly monitored and reported to the PSCC. This regular reporting continued throughout November and December 2025, and through to 06 January 2026. On 06 January 2026, the PSCC was informed that a small number of vehicles which had left the port of entry had had the UPS status incorrectly marked as completed and subsequently been released. It was agreed to refer this to the Decision Forum. On 07 January 2026, the PSCC Decision Forum agreed that a safety recall should be launched to correct the labels at the earliest opportunity. JLR has received 0 claims and field reports in the US. There have been no reported accidents, injuries or fires in the US as a result of this concern.

Related NHTSA Recall Number:

Description of Remedy

Remedy Type: Replace

Consumer Advisories: Do Not Drive Park Outside

Description of remedy program:

The vehicle will have the certification label replaced. There will be no charge to the owners for this permanent repair.

How remedy component differs from recalled component:

Identify how/when recall condition was corrected in production:

Reimbursement Plan

Manufacturer used general reimbursement plan on file.

Recall Schedule

Description of recall schedule:

Retailer notification will occur on or before 23JAN26. Customer Letters will be mailed on or before 6MAR26.

Planned Dealer Notification Date: Jan 23, 2026 - Jan 23, 2026 No Dealers

Planned Interim Owner Notification Date: No Owners

Part 573 Safety Recall Report

26V005

Planned Remedy Owner Notification Date: Mar 06, 2026 - Mar 06, 2026 Phased Recall

Date when VIN will be searchable: Mar 06, 2026