



U.S. Department  
of Transportation

National Highway  
Traffic Safety  
Administration

## Part 573 Safety Recall Report

# 26V171

**Manufacturer Name:** Braun Corporation

**Submission Date:** Mar 20, 2026

**NHTSA Recall No.:** 26V171

**Manufacturer Recall No.:**

### Manufacturer Information

### Population

**Manufacturer Name:** Braun Corporation

**Address:** 631 West 11 Street  
Winamac IN, 46996

**Total number of potentially involved:** 13

**Estimated percentage with defect:** 100%

### Vehicle Information

**Vehicle 1:** 2023-2023 BRAUN RAM PROMASTER

**Product Category:** Light Vehicles

**Product Type:**

**Fuel / Propulsion:**

**Production Dates:** Aug 01, 2023 - Sep 12, 2023

**Number of potentially involved:** 8

**Descriptive Information:**

It was discovered that the emergency window in some Promaster units are not FMVSS 226 compliant.

**Vehicle 2:** 2024-2024 BRAUN RAM PROMASTER

**Product Category:** Light Vehicles

**Product Type:**

**Fuel / Propulsion:**

**Production Dates:** Mar 20, 2024 - Mar 22, 2024

**Number of potentially involved:** 5

**Descriptive Information:**

It was discovered that the emergency window in some Promaster units are not FMVSS 226 compliant.

### Defect / Noncompliance Description

**Description of the defect or noncompliance:**

# Part 573 Safety Recall Report

**26V171**

The emergency window in some Promaster units are not FMVSS 226 compliant.

**FMVSS1:**

**FMVSS2:**

**Description of the safety risk, including crash, fire, death, injury:**

Ejection mitigation cannot be guaranteed.

**Description of the cause:**

Emergency window used was not manufactured to FMVSS226 standards.

**Identification of any warning that can occur:**

none

## Component Manufacturer

**Tier of Supplier:** Tier 1

**Supplier Type:** Distributor

**Name:** CR Laurence Co. Inc.

**Address:** 2503 E Vernon Ave  
Los Angeles CA, 90058-1826

**Country:** United States

## Involved Components

**Component Name 1:** Emergency Window

**Component Description:** Emergency Window

**Component Part Number:** TX11298

## Chronology

**Related NHTSA Recall Number:**

# Part 573 Safety Recall Report

# 26V171

## Description of Remedy

**Remedy Type:** Replace

**Consumer Advisories:**  Do Not Drive  Park Outside

**Description of remedy program:**

Trained technician will replace the window with FMVSS 226 compliant windows.

**How remedy component differs from recalled component:**

Will be FMVSS 226 compliant

**Identify how/when recall condition was corrected in production:**

There were a limited number produced with this optional window. We discovered the issue after exploring options for future products with emergency windows in March 2026.

## Reimbursement Plan

**Description of reimbursement program:**

Parts, Labor and Shipping costs to remediate this issue will be paid by BraunAbility to customer or the repairer.

**Period of reimbursement:**

Until 100% of recall completion

**Costs to be reimbursed:**

All costs to customer to have remedy completed will be reimbursed at the invoiced repair amount.

**Address for reimbursement claims:**

631 W 11th Street  
Winamac IN, 46996

## Recall Schedule

**Description of recall schedule:**

Dealers and customers will be notified of the recall via required methods.

**Planned Dealer Notification Date:** Apr 13, 2026 - May 13, 2026  No Dealers

**Planned Interim Owner Notification Date:**  No Owners

# Part 573 Safety Recall Report

**26V171**

**Planned Remedy Owner Notification Date:** Apr 13, 2026 - May 13, 2026  Phased Recall

**Date when VIN will be searchable:**