



U.S. Department
of Transportation

National Highway
Traffic Safety
Administration

Part 573 Safety Recall Report

26V173

Manufacturer Name: Kia America, Inc.

Submission Date: Mar 20, 2026

NHTSA Recall No.: 26V173

Manufacturer Recall No.: SC366

Manufacturer Information

Population

Manufacturer Name: Kia America, Inc.

Address: 111 Peters Canyon Road
Irvine CA, 92606

Total number of potentially involved: 568

Estimated percentage with defect: 100%

Vehicle Information

Vehicle 1: 2027-2027 KIA TELLURIDE HYBRID

Product Category: Light Vehicles

Product Type: Multipurpose Passenger Vehicle

Fuel / Propulsion: Hybrid Electric Vehicle

Production Dates: Feb 02, 2026 - Mar 13, 2026

Number of potentially involved: 568

Descriptive Information:

Certain 2027 model year Kia Telluride Hybrid SX Prestige and X-Line SX Prestige vehicles equipped with the optional Executive Package manufactured from February 2, 2026 to March 13, 2026 (568 units).

The recall population was determined by a review of Kia vehicle production records. The vehicles subject to this recall were not produced in VIN order. Customers seeking information about their specific vehicle will be referred to Kia's Customer Care Center or their Kia dealer.

Defect / Noncompliance Description

Description of the defect or noncompliance:

The power second-row seat assemblies, which have an automatic power-folding (stow) and "one-touch" tilt-and-slide (walk-in) feature, may not detect obstructions and may continue to move if these features are used while an occupant is in the seat or is entering/exiting the rear of the vehicle.

FMVSS1:

FMVSS2:

Description of the safety risk, including crash, fire, death, injury:

Part 573 Safety Recall Report

26V173

If the seat does not detect an occupant, the risk of injury may increase.

Description of the cause:

Cause is currently under review

Identification of any warning that can occur:

None

Component Manufacturer

Tier of Supplier: Tier 2

Supplier Type: OEM

Name: Nidec Mobility Korea Corporation

Address: 790-12, Bogaewonsam-ro,
Bogae-myeon, Gyeonggi-do
Anseong-si Foreign States, 17507

Country: Korea, Republic Of

Involved Components

Component Name 1: UNIT ASSY-RR POWER, LH

Component Description: Power Rear Seat Control Unit Assembly, LH

Component Part Number: 891P8-P8000

Component Name 2: UNIT ASSY-RR POWER, RH

Component Description: Power Rear Seat Control Unit Assembly, RH

Component Part Number: 892P8-P8000

Chronology

See attached document titled "2027MY Telluride Hybrid Power Second-Row Seat Assembly Chronology"

Related NHTSA Recall Number:

Part 573 Safety Recall Report

26V173

Description of Remedy

Remedy Type:

Consumer Advisories: Do Not Drive Park Outside

Description of remedy program:

Remedy is under development. Kia advises customers to 1) ensure children are not in the rear seats or rear seating area during power-folding operation, and 2) avoid inadvertent pressing of the power second-row seat switches.

How remedy component differs from recalled component:

TBD

Identify how/when recall condition was corrected in production:

TBD

Reimbursement Plan

Manufacturer used general reimbursement plan on file.

Recall Schedule

Description of recall schedule:

The planned dealer notification begin and end date is March 20, 2026. The planned interim owner notification begin and end date is April 6, 2026. The planned remedy owner notification begin and end date is May 19, 2026.

Planned Dealer Notification Date: Mar 20, 2026 - Mar 20, 2026 No Dealers

Planned Interim Owner Notification Date: Apr 06, 2026 - Apr 06, 2026 No Owners

Planned Remedy Owner Notification Date: May 19, 2026 - May 19, 2026 Phased Recall

Date when VIN will be searchable: Mar 25, 2026