



U.S. Department  
of Transportation

National Highway  
Traffic Safety  
Administration

## Part 573 Safety Recall Report

## 26V177

**Manufacturer Name:** Winnebago Industries, Inc.

**Submission Date:** Mar 23, 2026

**NHTSA Recall No.:** 26V177

**Manufacturer Recall No.:** 203

### Manufacturer Information

### Population

**Manufacturer Name:** Winnebago Industries, Inc.

**Address:** PO BOX 152  
605 W. Crystal Lake Rd.  
Forest City IA, 50436

**Total number of potentially involved:** 1,446

**Estimated percentage with defect:** 100%

### Vehicle Information

**Vehicle 1:** 2017-2017 WINNEBAGO BRAVE

**Product Category:** Buses, Medium & Heavy Vehicles

**Product Type:**

**Fuel / Propulsion:**

**Production Dates:** Mar 14, 2016 - Mar 14, 2016

**Number of potentially involved:** 1

**Descriptive Information:**

The population was determined by the production date.

**Vehicle 2:** 2019-2019 ITASCA SUNOVA

**Product Category:** Buses, Medium & Heavy Vehicles

**Product Type:**

**Fuel / Propulsion:**

**Production Dates:** Apr 03, 2018 - Aug 27, 2018

**Number of potentially involved:** 21

**Descriptive Information:**

The population was determined by the production dates.

**Vehicle 3:** 2019-2022 WINNEBAGO ADVENTURER

**Product Category:** Buses, Medium & Heavy Vehicles

**Part 573 Safety Recall Report****26V177****Product Type:****Fuel / Propulsion:****Production Dates:** Jun 12, 2018 - May 01, 2023**Number of potentially involved:** 1,297**Descriptive Information:**

The population was determined by production dates.

**Vehicle 4:** 2022-2022 WINNEBAGO SUNSTAR**Product Category:** Buses, Medium & Heavy Vehicles**Product Type:****Fuel / Propulsion:****Production Dates:** Apr 01, 2021 - Nov 15, 2022**Number of potentially involved:** 127**Descriptive Information:**

The population was determined by production dates.

**Defect / Noncompliance Description****Description of the defect or noncompliance:**

Certain Winnebago vehicles are equipped with front turn signal lamps that do not meet the luminous lens area requirements. As such these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard FMVSS No. 108, "Lamps, Reflective Devices, and Associated Equipment."

**FMVSS1:** 108 - Lamps, reflective devices, and assoc. Equipment**FMVSS2:****Description of the safety risk, including crash, fire, death, injury:**

The failure to be equipped with turn signals compliant with FMVSS No. 108, "Lamps, Reflective Devices, and Associated Equipment", reduces other road users' visibility of the signal lamps. Reduced visibility may lead roadway users to misunderstand the intent to turn or make lane changes which increases the risk of a crash.

**Description of the cause:**

The turn signals in certain Winnebago vehicles are smaller than the required minimum lens area.

**Identification of any warning that can occur:**

# Part 573 Safety Recall Report

# 26V177

## Component Manufacturer

**Tier of Supplier:** Tier 1

**Supplier Type:**

**Name:** Kaper II Inc

**Address:** 2212 ½ Parrott Way PO Box 449  
Kelso WA, 98626

**Country:** United States

## Involved Components

**Component Name 1:** Lamp ASM – PARK/TURN or Turn Signal

**Component Description:** Lamp ASM – PARK/TURN or Turn Signal

**Component Part Number:** 146560-1SV4710C/A

## Chronology

In February 2026, while finalizing the repair for recall 24V-733, an additional population of vehicles failed to comply with the requirements of Federal Motor Vehicle Safety Act CMVSS No. 108, "Lamps, Reflective Devices, and Associated Equipment." On March 16, the topic was escalated to the Product Safety Committee who voted to expand the recall population. An inquiry was conducted with NHTSA regarding clarification on expanding the previous recall or filing a new recall. Winnebago was advised to submit a new recall. Winnebago is not aware of any complaints, warranty claims, accidents, injuries, or property damage because of this condition.

**Related NHTSA Recall Number:** 24V733

## Description of Remedy

**Remedy Type:** Replace

**Consumer Advisories:**  Do Not Drive  Park Outside

**Description of remedy program:**

Reimbursement requests will follow the general reimbursement plan on file with NHTSA.

# Part 573 Safety Recall Report

**26V177****How remedy component differs from recalled component:**

The remedy involves replacing the non-compliant lights with new lights that comply with Federal Motor Vehicle Safety Standard FMVSS No. 108, "Lamps, Reflective Devices, and Associated Equipment."

**Identify how/when recall condition was corrected in production:**

Winnebago Motorhomes no longer installs the non-compliant lights.

## Reimbursement Plan

Manufacturer used general reimbursement plan on file.

## Recall Schedule

**Description of recall schedule:**

**Planned Dealer Notification Date:** Mar 31, 2026 - Mar 31, 2026  No Dealers

**Planned Interim Owner Notification Date:**  No Owners

**Planned Remedy Owner Notification Date:** May 01, 2026 - May 01, 2026  Phased Recall

**Date when VIN will be searchable:**