



U.S. Department
of Transportation

National Highway
Traffic Safety
Administration

Part 573 Safety Recall Report

26V181

Manufacturer Name: Bentley Motors, Inc.

Submission Date: Mar 24, 2026

NHTSA Recall No.: 26V181

Manufacturer Recall No.: RE26/05

Manufacturer Information

Population

Manufacturer Name: Bentley Motors, Inc.

Address: 2200 Ferdinand Porsche
Drive
Herndon VA, 20171

Total number of potentially involved: 44

Estimated percentage with defect: 100%

Vehicle Information

Vehicle 1: 2025-2025 BENTLEY BENTAYGA

Product Category: Light Vehicles

Product Type: Multipurpose Passenger Vehicle

Fuel / Propulsion: Spark Ignition Fuel

Production Dates: Sep 28, 2024 - Jul 15, 2025

Number of potentially involved: 44

Descriptive Information:

Affected vehicles have been identified using internal production records.

Vehicles not included in the recall are fitted with the correct specification tire information placard.

Defect / Noncompliance Description

Description of the defect or noncompliance:

Certain Bentley Bentayga vehicles fail to comply with the requirements of the Federal Motor Vehicle Safety Standard No. 110 " Tire selection and Rims". The tire information placard fitted may list the incorrect tire size and cold inflation pressures for the tires fitted to the vehicle at the time of first purchase.

FMVSS1:

FMVSS2:

Description of the safety risk, including crash, fire, death, injury:

Owners may be incorrectly informed of the required tire size and cold inflation pressures of the tires

Part 573 Safety Recall Report

26V181

fitted to the vehicle at the time of first purchase.
This could cause owners to select the incorrect replacement tires or utilize incorrect cold inflation pressures, increasing the risk of an accident.

Description of the cause:

A configuration error occurred during the coding of the production system, this resulted in the incorrect tire information placard being assigned to a singular specification of vehicle.

Identification of any warning that can occur:

None

Component Manufacturer

Tier of Supplier: Tier 1

Supplier Type: OEM

Name: Bentley Motors

Address: Pyms Lane
Crewe Foreign States, CW1 3PL

Country: United Kingdom

Involved Components

Component Name 1: Tire Placard

Component Description: Tire Information Placard

Component Part Number: 36B.010.000.LM

Chronology

14/10/2025 - Bentley identified a coding error within the production control system for a single specification of Bentley vehicle.

15/10/2025 - Coding error was corrected in production control system. Affected factory vehicles identified and held.

16/10/2025 - Product safety investigation opened.

16/10/2025 - 17/03/2026 - Thorough analysis of all retailed vehicle specifications since market entry to determine affected scope.

18/03/2026 - Investigation results presented to Bentley Product Safety Committee where determination of a Non-Compliance to FMVSS 110 was made.

Part 573 Safety Recall Report

26V181

Related NHTSA Recall Number:

Description of Remedy

Remedy Type: Replace**Consumer Advisories:** Do Not Drive Park Outside**Description of remedy program:**

Bentley authorized dealers will replace the incorrect tire information placard with the correct version. This will take approximately 30 minutes to complete and will be completed free of charge. Because the affected vehicles are still within the warranty period, Bentley will not offer a reimbursement program under this recall.

How remedy component differs from recalled component:

The correct version of the tire information placard, containing the correct tire size and cold inflation pressures.

Identify how/when recall condition was corrected in production:

Coding configuration of the production control system was updated to specify the correct tire information placard for the affected vehicle specification.

Reimbursement Plan

Description of reimbursement program:

There is no plan for reimbursement, as all vehicles affected are still within the manufacturer's 3-year warranty agreement.

Period of reimbursement:**Costs to be reimbursed:****Address for reimbursement claims:**

Recall Schedule

Description of recall schedule:

Bentley expects dealer notification to occur on or before April 27, 2026 and owner notification to occur on or before May 4, 2026.

Part 573 Safety Recall Report**26V181****Planned Dealer Notification Date:** Apr 27, 2026 - Apr 28, 2026 No Dealers**Planned Interim Owner Notification Date:** No Owners**Planned Remedy Owner Notification Date:** May 04, 2026 - May 08, 2026 Phased Recall**Date when VIN will be searchable:**