



U.S. Department
of Transportation

National Highway
Traffic Safety
Administration

Part 573 Safety Recall Report

26V241

Manufacturer Name: Winnebago Industries, Inc.

Submission Date: Apr 15, 2026

NHTSA Recall No.: 26V241

Manufacturer Recall No.: 204

Manufacturer Information

Population

Manufacturer Name: Winnebago Industries, Inc.

Address: PO BOX 152
605 W. Crystal Lake Rd.
Forest City IA, 50436

Total number of potentially involved: 20

Estimated percentage with defect: 100%

Vehicle Information

Vehicle 1: 2027-2027 WINNEBAGO SUNCRUISER

Product Category: Buses, Medium & Heavy Vehicles

Product Type: Recreational Vehicle

Fuel / Propulsion:

Production Dates: Mar 06, 2026 - Mar 06, 2026

Number of potentially involved: 1

Descriptive Information:

The population was determined by the Build Production Dates.

Vehicle 2: 2026-2027 WINNEBAGO SUNFLYER

Product Category: Buses, Medium & Heavy Vehicles

Product Type: Recreational Vehicle

Fuel / Propulsion:

Production Dates: Aug 26, 2025 - Feb 06, 2026

Number of potentially involved: 19

Descriptive Information:

The population was determined by the Build Production dates.

Defect / Noncompliance Description

Part 573 Safety Recall Report

26V241

Description of the defect or noncompliance:

Certain Winnebago Vehicles are not equipped with required side marker reflex reflectors. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard FMVSS 108, "Lamps, Reflective Devices, and Associated Equipment."

FMVSS1: 108 - Lamps, reflective devices, and assoc. Equipment

FMVSS2:

Description of the safety risk, including crash, fire, death, injury:

The absence of side marker reflex reflectors reduces the vehicle's conspicuity to other road users in low-light and night-time conditions, increasing the risk of a crash.

Description of the cause:

During production, the required side marker reflex reflectors were inadvertently omitted from the affected vehicles.

Identification of any warning that can occur:

None. The absence of the reflectors is not accompanied by any warning indicator or symptom noticeable to the driver.

Component Manufacturer

Tier of Supplier:

Supplier Type:

Name: Winnebago Industries

Address: 605 West Crystal Lake Road
Forest City IA, 50436

Country: United States

Involved Components

Component Name 1: REFLECTOR-RECT,STK ON,RED

Component Description: REFLECTOR-RECT,STK ON,RED

Component Part Number: 166850-01-000

Chronology

Part 573 Safety Recall Report

26V241

On April 8, 2026, during an engineering review, it was identified that side marker reflex reflectors had been omitted from certain vehicles.

On April 9, 2026, the Product Safety Committee reviewed this issue and approved the need for a Recall.

Related NHTSA Recall Number:

Description of Remedy

Remedy Type: Repair

Consumer Advisories: Do Not Drive Park Outside

Description of remedy program:

Reimbursement requests will follow the general reimbursement plan on file with NHTSA.

How remedy component differs from recalled component:

Authorized dealers will install the required red marker light on affected vehicles at no cost to the owner.

Identify how/when recall condition was corrected in production:

A design engineering change has been implemented in production to include the required reflectors on all vehicles going forward. A rework campaign has been issued for affected vehicles currently in inventory.

Reimbursement Plan

Manufacturer used general reimbursement plan on file.

Recall Schedule

Description of recall schedule:

Planned Dealer Notification Date: May 08, 2026

No Dealers

Planned Interim Owner Notification Date:

No Owners

Planned Remedy Owner Notification Date: Jun 08, 2026

Phased Recall

Part 573 Safety Recall Report

26V241

Date when VIN will be searchable: