



U.S. Department
of Transportation

National Highway
Traffic Safety
Administration

Part 573 Safety Recall Report

26V279

Manufacturer Name: New Flyer of America, Inc.

Submission Date: May 01, 2026

NHTSA Recall No.: 26V279

Manufacturer Recall No.:

Manufacturer Information

Population

Manufacturer Name: New Flyer of America, Inc.

Address: 711 Kernaghan Avenue
Winnipeg, MB FS, R2C3T4

Total number of potentially involved: 4

Estimated percentage with defect: 100%

Vehicle Information

Vehicle 1: 2022-2022 NEW FLYER XE40

Product Category: Buses, Medium & Heavy Vehicles

Product Type:

Fuel / Propulsion: Electric Battery Power

Production Dates: Dec 01, 2022 - Apr 13, 2026

Number of potentially involved: 4

Descriptive Information:

Buses are a single order. Other buses not included are not part of this order.

Defect / Noncompliance Description

Description of the defect or noncompliance:

The buses did not have an illuminated speedometer when the headlamps were turned on.

FMVSS1: 101 - Control and displays

FMVSS2:

Description of the safety risk, including crash, fire, death, injury:

In nighttime operation, without an illuminated speedometer, a driver may not know the speed they are driving, which could increase the risk of a crash.

Description of the cause:

Part 573 Safety Recall Report

26V279

The programming used an incorrect signal which did not illuminate the speedometer.

Identification of any warning that can occur:

Component Manufacturer

Tier of Supplier:

Supplier Type:

Name:

Address:

Country:

Involved Components

Component Name 1: Dash cluster

Component Description: MODULE-IP 40' MPH W/TOUCH SCREEN

Component Part Number: 517431

Chronology

- 17-Apr-2026, during Early Warning Report generation, a Field Report from Mar-2026 was identified that indicated the dash lamps were not illuminated during night-run on an order of buses.
- 20 to 24-Apr-2026 information was gathered to verify the issue and was determined to be an incorrect program.
- 27-Apr-2026 the issue was raised to the Vehicle Safety Committee culminating in a consensus to issue a noncompliance recall.

Related NHTSA Recall Number:

Description of Remedy

Remedy Type: Software

Part 573 Safety Recall Report

26V279

Consumer Advisories: Do Not Drive Park Outside

Description of remedy program:

New Flyer will provide updated software free of charge.

How remedy component differs from recalled component:

Identify how/when recall condition was corrected in production:

Reimbursement Plan

Manufacturer used general reimbursement plan on file.

Recall Schedule

Description of recall schedule:

Planned Dealer Notification Date: No Dealers

Planned Interim Owner Notification Date: No Owners

Planned Remedy Owner Notification Date: Jun 15, 2026 - Jun 15, 2026 Phased Recall

Date when VIN will be searchable: