



U.S. Department  
of Transportation

National Highway  
Traffic Safety  
Administration

## Part 573 Safety Recall Report

## 26V336

**Manufacturer Name:** Forest River, Inc.

**Submission Date:** May 26, 2026

**NHTSA Recall No.:** 26V336

**Manufacturer Recall No.:** 51-2062

### Manufacturer Information

### Population

**Manufacturer Name:** Forest River, Inc.

**Address:** 55470 CR 1  
P.O. Box 3030  
Elkhart IN, 46515-3030

**Total number of potentially involved:** 200

**Estimated percentage with defect:** 100%

### Vehicle Information

**Vehicle 1:** 2026-2026 FOREST RIVER RIVERSTONE

**Product Category:** Trailers

**Product Type:** Recreational Trailers

**Fuel / Propulsion:**

**Production Dates:** Jan 29, 2026 - Feb 17, 2026

**Number of potentially involved:** 2

**Descriptive Information:**

Certain 2026 Riverstone: RSF420RE & RSF43BFC

The scope was determined using sales records from the supplier.

**Vehicle 2:** 2026-2026 FOREST RIVER CEDAR CREEK

**Product Category:** Trailers

**Product Type:** Recreational Trailers

**Fuel / Propulsion:**

**Production Dates:** Sep 22, 2025 - May 08, 2026

**Number of potentially involved:** 191

**Descriptive Information:**

Certain 2026 Cedar Creek: CRF29RL, CRF361RL, CRF370FL, CRF381MUD, CRF383FB, CRF385RK, CRF38DB & CRF39RKB.

The scope was determined using sales records from the supplier.

# Part 573 Safety Recall Report

# 26V336

**Vehicle 3:** 2024-2024 FOREST RIVER R-POD

**Product Category:** Trailers

**Product Type:** Recreational Trailers

**Fuel / Propulsion:**

**Production Dates:** Sep 01, 2023 - Dec 21, 2023

**Number of potentially involved:** 7

**Descriptive Information:**

Certain 2024 R. POD: NBT16.6, NBT19.5, NBT20.3, RPT202 & RPT203.

The scope was determined using sales records from the supplier.

## Defect / Noncompliance Description

**Description of the defect or noncompliance:**

According to the LCI Campaign: "CURT® Touring Coil Suspension (TCS) shock bolts may have been improperly torqued during installation."

**FMVSS1:**

**FMVSS2:**

**Description of the safety risk, including crash, fire, death, injury:**

According to Lippert's Recall 26E032: "Under certain operating conditions, if the bolt head fractures while the vehicle is in motion, the bolt head and retaining washer may loosen or detach causing road debris, potentially increasing the risk of vehicle crash."

**Description of the cause:**

Vendor Component

**Identification of any warning that can occur:**

N/A

## Component Manufacturer

**Tier of Supplier:** Tier 1

**Supplier Type:** OEM

**Name:** Lippert

# Part 573 Safety Recall Report

**26V336**

**Address:** 2020 Blakesley Pkwy  
Bristol IN, 46507

**Country:** United States

## Involved Components

**Component Name 1:** Curt Touring Coil Suspension

**Component Description:** 3/8" - 16 x 3/4" HWH ZN HEX 3L ST (Grade 5)

**Component Part Number:** 298315

## Chronology

On May 8, 2026, Forest River's Office of Corporate Compliance was notified by LCI of their Technical Service Bulletin, 019-001-2026.

On May 11, 2026, OCC began researching if the components had been used in manufacturing.

On May 20, 2026, OCC received a notice of recall pertaining to this concern from LCI.

On May 26, 2026, OCC finished identifying affected vehicles with the Curt Touring Coil Suspension.

**Related NHTSA Recall Number:** 26E032

## Description of Remedy

**Remedy Type:** Replace

**Consumer Advisories:**  Do Not Drive  Park Outside

**Description of remedy program:**

Forest River will provide all parts and labor free of charge to Consumers and Dealers. An authorized Forest River dealer will need to perform the remedy as prescribed for the Curt Touring Coil Suspension.

What is the Forest River Customer Service Phone Number?

Cedar Creek: (260) 593-4000

R. POD: 574-642-3119

Riverstone: 260-593-4028

LCI: 574-312-6825

If you have already paid for a repair that is within the scope of this defect under recall, you still need to have this recall inspected and/or performed to ensure the correct parts and procedures were utilized. Additionally, you may be eligible for a refund of previously paid repairs. Refunds will only be provided for within the scope of this defect under recall.

Please send the service invoice to the following address:

# Part 573 Safety Recall Report

# 26V336

ar Creek  
Forest River, Inc.  
Attn: WARRANTY MANAGER  
501 Hawpatch Dr.  
Topeka, IN 46571

R. POD/NO BO/IBEX  
Attn: WARRANTY MANAGER  
1492 Gerber St.  
Ligonier, IN 46767

Riverstone  
Attn: WARRANTY MANAGER  
406 Lehman Dr.  
Topeka, IN 46571

Lippert  
Attn: Director of Product Warranty  
2020 Blakesley Pkwy  
Bristol, IN, 46507

## How remedy component differs from recalled component:

The self-threading 3/8" - 16 x 3/4" HWH ZN HEX 3L ST (Grade 5) will be replaced with a 3/8" - 16 x 3/4" Grade 8 (16 pcs.), which is properly torqued.

## Identify how/when recall condition was corrected in production:

Unknown.

## Reimbursement Plan

Manufacturer used general reimbursement plan on file.

## Recall Schedule

### Description of recall schedule:

Forest River has the utmost urgency in our recalls. Forest River will send suspected VIN numbers to our third party vendor that is licensed to pull data on the current owner of the vehicles (as needed) once a formal NHTSA I.D. is provided. Forest River intends on pushing the mailing out as soon as NHTSA provides any correction(s) and an Acknowledgement Letter.

**Planned Dealer Notification Date:** Jun 01, 2026 - Jul 02, 2026

No Dealers

**Planned Interim Owner Notification Date:**

No Owners

**Planned Remedy Owner Notification Date:** Jun 01, 2026 - Jul 02, 2026

Phased Recall

**Date when VIN will be searchable:**