



U.S. Department
of Transportation

National Highway
Traffic Safety
Administration

Part 573 Safety Recall Report

26V336

Manufacturer Name: Forest River, Inc.

Submission Date: Jul 06, 2026

NHTSA Recall No.: 26V336

Manufacturer Recall No.: 51-2062

Manufacturer Information

Population

Manufacturer Name: Forest River, Inc.

Address: 55470 CR 1
P.O. Box 3030
Elkhart IN, 46515-3030

Total number of potentially involved: 200

Estimated percentage with defect: 100%

Vehicle Information

Vehicle 1: 2026-2026 FOREST RIVER CEDAR CREEK

Product Category: Trailers

Product Type: Recreational Trailers

Fuel / Propulsion:

Production Dates: Sep 22, 2025 - May 08, 2026

Number of potentially involved: 191

Descriptive Information:

Certain 2026 Cedar Creek: CRF29RL, CRF361RL, CRF370FL, CRF381MUD, CRF383FB, CRF385RK, CRF38DB & CRF39RKB.

The scope was determined using sales records from the supplier.

Vehicle 2: 2024-2024 FOREST RIVER R-POD

Product Category: Trailers

Product Type: Recreational Trailers

Fuel / Propulsion:

Production Dates: Sep 01, 2023 - Dec 21, 2023

Number of potentially involved: 7

Descriptive Information:

Certain 2024 R. POD: NBT16.6, NBT19.5, NBT20.3, RPT202 & RPT203.

The scope was determined using sales records from the supplier.

Part 573 Safety Recall Report

26V336**Vehicle 3:** 2026-2026 FOREST RIVER RIVERSTONE**Product Category:** Trailers**Product Type:** Recreational Trailers**Fuel / Propulsion:****Production Dates:** Jan 29, 2026 - Feb 17, 2026**Number of potentially involved:** 2**Descriptive Information:**

Certain 2026 Riverstone: RSF420RE & RSF43BFC

The scope was determined using sales records from the supplier.

Defect / Noncompliance Description

Description of the defect or noncompliance:

According to the LCI Campaign: "CURT® Touring Coil Suspension (TCS) shock bolts may have been improperly torqued during installation."

FMVSS1:**FMVSS2:****Description of the safety risk, including crash, fire, death, injury:**

According to Lippert's Recall 26E032: "Under certain operating conditions, if the bolt head fractures while the vehicle is in motion, the bolt head and retaining washer may loosen or detach causing road debris, potentially increasing the risk of vehicle crash."

Description of the cause:

Vendor Component

Identification of any warning that can occur:

N/A

Component Manufacturer

Tier of Supplier: Tier 1**Supplier Type:** OEM**Name:** Lippert

Part 573 Safety Recall Report

26V336

Address: 2020 Blakesley Pkwy
Bristol IN, 46507

Country: United States

Involved Components

Component Name 1: Curt Touring Coil Suspension

Component Description: 3/8" - 16 x 3/4" HWH ZN HEX 3L ST (Grade 5)

Component Part Number: 298315

Chronology

On May 8, 2026, Forest River's Office of Corporate Compliance was notified by LCI of their Technical Service Bulletin, 019-001-2026.

On May 11, 2026, OCC began researching if the components had been used in manufacturing.

On May 20, 2026, OCC received a notice of recall pertaining to this concern from LCI.

On May 26, 2026, OCC finished identifying affected vehicles with the Curt Touring Coil Suspension.

On July 6, 2026, OCC amended the Planned Remedy Owner Notification Date due to unforeseen circumstances. The amended date is within the 60-day limit.

Related NHTSA Recall Number: 26E032

Description of Remedy

Remedy Type: Replace

Consumer Advisories: ☐ Do Not Drive ☐ Park Outside

Description of remedy program:

Forest River will provide all parts and labor free of charge to Consumers and Dealers. An authorized Forest River dealer will need to perform the remedy as prescribed for the Curt Touring Coil Suspension.

What is the Forest River Customer Service Phone Number?

Cedar Creek: (260) 593-4000

R. POD: 574-642-3119

Riverstone: 260-593-4028

LCI: 574-312-6825

If you have already paid for a repair that is within the scope of this defect under recall, you still need to have this recall inspected and/or performed to ensure the correct parts and procedures were utilized. Additionally, you may be eligible for a refund of previously paid repairs. Refunds will only be provided

Part 573 Safety Recall Report

26V336

for within the scope of this defect under recall.
Please send the service invoice to the following address:

ar Creek
Forest River, Inc.
Attn: WARRANTY MANAGER
501 Hawpatch Dr.
Topeka, IN 46571

R. POD/NO BO/IBEX
Attn: WARRANTY MANAGER
1492 Gerber St.
Ligonier, IN 46767

Riverstone
Attn: WARRANTY MANAGER
406 Lehman Dr.
Topeka, IN 46571

Lippert
Attn: Director of Product Warranty
2020 Blakesley Pkwy
Bristol, IN, 46507

How remedy component differs from recalled component:

The self-threading 3/8" - 16 x 3/4" HWH ZN HEX 3L ST (Grade 5) will be replaced with a 3/8" - 16 x 3/4" Grade 8 (16 pcs.), which is properly torqued.

Identify how/when recall condition was corrected in production:

Unknown.

Reimbursement Plan

Manufacturer used general reimbursement plan on file.

Recall Schedule

Description of recall schedule:

Forest River has the utmost urgency in our recalls. Forest River will send suspected VIN numbers to our third party vendor that is licensed to pull data on the current owner of the vehicles (as needed) once a formal NHTSA I.D. is provided. Forest River intends on pushing the mailing out as soon as NHTSA provides any correction(s) and an Acknowledgement Letter.

Planned Dealer Notification Date: Jul 05, 2026 - Jul 05, 2026

☐ No Dealers

Planned Interim Owner Notification Date:

☐ No Owners

Planned Remedy Owner Notification Date: Jul 05, 2026 - Jul 20, 2026

☐ Phased Recall

Part 573 Safety Recall Report

26V336

Date when VIN will be searchable: