



U.S. Department
of Transportation

National Highway
Traffic Safety
Administration

Part 573 Safety Recall Report

26V379

Manufacturer Name: Vermeer Manufacturing Company

Submission Date: Jun 09, 2026

NHTSA Recall No.: 26V379

Manufacturer Recall No.: IK4837

Manufacturer Information

Population

Manufacturer Name: Vermeer Manufacturing
Company
Address: 1210 VERMEER ROAD
EAST
PO BOX 200
PELLA IA, 50219-0200

Total number of potentially involved: 515
Estimated percentage with defect: 100%

Vehicle Information

Vehicle 1: 2002-2026 VERMEER BC1800XL

Product Category: Trailers

Product Type:

Fuel / Propulsion:

Production Dates: Jul 15, 2002 - Jun 03, 2026

Number of potentially involved: 515

Descriptive Information:

Using various manufacturing documents and drawings, as well as personnel records, research was conducted to identify the population of Brush Chippers potentially affected by a failure that can occur resulting in the extension of the hydraulic jack without input from the operator.

The recalled Brush Chippers may experience unintended extension of the hydraulic jack without operator input.

Defect / Noncompliance Description

Description of the defect or noncompliance:

A failure can occur, resulting in the extension of the hydraulic jack to extend without input from the operator.

FMVSS1:

Part 573 Safety Recall Report

26V379

FMVSS2:

Description of the safety risk, including crash, fire, death, injury:

When towing the brush chipper on public roadways, death or serious injury is possible if the hydraulic jack contacts the ground and causes loss of vehicle control or becomes separated and strikes another vehicle or pedestrian. Property damage is also possible.

Description of the cause:

Identification of any warning that can occur:

Component Manufacturer

Tier of Supplier:

Supplier Type:

Name:

Address:

Country:

Involved Components

Component Name 1: HYDRAULIC PUMP

Component Description: PUMP - DC POWER 3GPM@500PSI/RV@2500

Component Part Number: 151239001

Component Name 2: ELECTRICAL HYD. JACK ASSEMBLY

Component Description: ELECTRICAL HYD. JACK ASSEMBLY

Component Part Number: 180012333

Chronology

04/02/2026 Engineering contacted Product Safety to review customer field report of jack failure. Engineering and product safety determined further investigation was necessary.

Part 573 Safety Recall Report

26V379

04/08/2026 Engineering and Product Safety investigated electrical system and potential failure modes.

04/16/2026 Engineering and Service compiled historical field data for investigation and analysis.

05/15/2026 Service returned from Australia with failed parts.

05/20/2026 Engineering sent failed samples to the pump vendor for inspection and failure analysis.

06/04/2026 After reviewing the issue regarding the hydraulic jack field reports, Product Safety and Product Liability determined that a potential safety hazard exists, and a Product Safety Alert must be issued to the field.

Related NHTSA Recall Number:

Description of Remedy

Remedy Type: Repair, Replace

Consumer Advisories: Do Not Drive Park Outside

Description of remedy program:

Vermeer will prepare field remedy kits which will include the necessary parts and instructions to resolve the potential safety issues described above. These field remedy kits will be provided to authorized Vermeer dealers to install. Upon installation and receipt of a field remedy kit warranty claim, dealers will be reimbursed for the parts and labor. Owners will be notified of the potential safety risk and available field remedy kit by letter according to the product database records maintained by Vermeer Corporation.

How remedy component differs from recalled component:

Identify how/when recall condition was corrected in production:

Recall conditions were corrected in production on: TBD.
Current units on ship hold.

Reimbursement Plan

Description of reimbursement program:

Vermeer Corporation pays for all parts and labor for product safety field campaigns regardless of whether the machine is still covered by its one-year standard limited warranty or whether the warranty has expired. Vermeer Corporation will reimburse a retail customer/machine owner when the owner has paid for repairs prior to the product safety field campaign. Owner must provide proof of repair. For an owner to obtain reimbursement, owner must inquire with an authorized, independent Vermeer dealer.

Period of reimbursement:

Part 573 Safety Recall Report

26V379

Vermeer Corporation pays for all parts and labor for product safety field campaigns regardless of whether the machine is still covered by its one-year standard limited warranty or whether the warranty has expired.

Costs to be reimbursed:

Vermeer Corporation pays for all parts and labor for product safety field campaigns regardless of whether the machine is still covered by its one-year standard limited warranty or whether the warranty has expired. Vermeer Corporation will reimburse a retail customer/machine owner when the owner has paid for repairs prior to the product safety field campaign. Owner must provide proof of repair. For an owner to obtain reimbursement, owner must inquire with an authorized, independent Vermeer dealer.

Address for reimbursement claims:

Recall Schedule

Description of recall schedule:

Dealer notification will begin 07/24/2026 by email with a list of affected machines in their area of responsibility. Owner notification letters will be sent 08/07/2026, with translated letters where necessary for their affected units.

Planned Dealer Notification Date: Jul 24, 2026 - Jul 24, 2026

No Dealers

Planned Interim Owner Notification Date:

No Owners

Planned Remedy Owner Notification Date:

Phased Recall

Date when VIN will be searchable: