



U.S. Department
of Transportation

National Highway
Traffic Safety
Administration

Part 573 Safety Recall Report

26V387

Manufacturer Name: Kawasaki Motors Corp., U.S.A.

Submission Date: Jun 12, 2026

NHTSA Recall No.: 26V387

Manufacturer Recall No.:

Manufacturer Information

Population

Manufacturer Name: Kawasaki Motors Corp.,
U.S.A.
Address: PO Box 25252
Santa Ana CA, 92799-5252

Total number of potentially involved: 840
Estimated percentage with defect: 1%

Vehicle Information

Vehicle 1: 2025-2026 KAWASAKI W230

Product Category: Motorcycles

Product Type: Motorcycles

Fuel / Propulsion: Compressed Natural Gas

Production Dates: Oct 02, 2024 - Oct 28, 2025

Number of potentially involved: 840

Descriptive Information:

The recall population consists of certain Model Year 2025-2026 BJ230A (W230 ABS) models. The recall population was determined by the beginning and ending production date for the models affected.

Defect / Noncompliance Description

Description of the defect or noncompliance:

Due to improper process controls during the manufacturing of turn signal lamp bulbs, some bulbs may contain foreign material or have cracks. As a result, the bulb filament may be damaged prematurely, which may cause the front and/or rear turn signal lamps to fail to illuminate.

FMVSS1:

FMVSS2:

Description of the safety risk, including crash, fire, death, injury:

Turn signal(s) that do not illuminate to indicate the direction of travel may increase the risk of a crash.

Part 573 Safety Recall Report

26V387**Description of the cause:**

Improper process control in the manufacturing process of signal lamp bulb.

Identification of any warning that can occur:

Component Manufacturer

Tier of Supplier:**Supplier Type:**

Name: Fiem Industries Ltd.

Address: Sector 48
Sonipat, Haryana Foreign States, 131028

Country: India

Involved Components

Component Name 1:**Component Description:****Component Part Number:**

Chronology

Related NHTSA Recall Number:

Description of Remedy

Remedy Type:

Consumer Advisories: Do Not Drive Park Outside

Description of remedy program:

Part 573 Safety Recall Report**26V387**

How remedy component differs from recalled component:

Identify how/when recall condition was corrected in production:

Reimbursement Plan**Recall Schedule**

Description of recall schedule:

Planned Dealer Notification Date:

No Dealers

Planned Interim Owner Notification Date:

No Owners

Planned Remedy Owner Notification Date:

Phased Recall

Date when VIN will be searchable: