



U.S. Department
of Transportation

National Highway
Traffic Safety
Administration

Part 573 Safety Recall Report

26V529

Manufacturer Name: Chrysler (FCA US, LLC)

Submission Date: Aug 13, 2026

NHTSA Recall No.: 26V529

Manufacturer Recall No.: 77D

Manufacturer Information

Population

Manufacturer Name: Chrysler (FCA US, LLC)

Address: 800 Chrysler Drive
CIMS 482-00-91
Auburn Hills MI, 48326-
2757

Total number of potentially involved: 81

Estimated percentage with defect: 100%

Vehicle Information

Vehicle 1: 2026-2026 JEEP GRAND CHEROKEE

Product Category: Light Vehicles

Product Type:

Fuel / Propulsion:

Production Dates: Jun 25, 2025 - May 11, 2026

Number of potentially involved: 57

Descriptive Information:

Some 2026 MY Jeep Grand Cherokee vehicles may have been built or flashed with Body Control Module ("BCM") software which may cause the windshield wipers to become inoperable under certain conditions.

The suspect period began on June 25, 2025, when the first vehicle that subsequently received a suspect software update was built, and ended on May 11, 2026, when the last vehicle with suspect software was built. The suspect population was determined through vehicle production and service records.

Similar vehicles not included in this recall were not built with suspect BCM software or were not subsequently flashed with suspect BCM software.

Vehicle 2: 2026-2026 JEEP GRAND CHEROKEE L

Product Category: Light Vehicles

Product Type:

Fuel / Propulsion:

Production Dates: Jul 21, 2025 - May 11, 2026

Number of potentially involved: 24

Part 573 Safety Recall Report

26V529

Descriptive Information:

Some 2026 MY Jeep Grand Cherokee L vehicles may have been built or flashed with BCM software which may cause the windshield wipers to become inoperable under certain conditions.

The suspect period began on July 21, 2025, when the first vehicle that subsequently received a suspect software update was built, and ended on May 11, 2026, when the last vehicle with suspect software was built. The suspect population was determined through vehicle production and service records.

Similar vehicles not included in this recall were not built with suspect BCM software or were not subsequently flashed with suspect BCM software.

Defect / Noncompliance Description

Description of the defect or noncompliance:

Suspect BCM software may cause the windshield wipers to become inoperable under certain conditions.

FMVSS1:

FMVSS2:

Description of the safety risk, including crash, fire, death, injury:

Windshield wipers which become inoperable may reduce forward visibility which can cause a vehicle crash without prior warning.

Description of the cause:

Identification of any warning that can occur:

None

Component Manufacturer

Tier of Supplier:

Supplier Type:

Name: Aptiv

Address: 5725 Innovation Dr
Troy MI, 48098

Country: United States

Involved Components

Part 573 Safety Recall Report

26V529

Component Name 1: Software

Component Description: BCM Software

Component Part Number: 68621876AK

Chronology

- On June 18, 2026, the FCA US LLC ("FCA US") Technical Safety and Regulatory Compliance ("TSRC") organization opened an investigation into some 2026 MY Jeep Grand Cherokee and Grand Cherokee L vehicles with a software issue which may disable windshield wiper functionality.
- From June 2026 through July 2026, FCA US TSRC met with FCA US engineering and manufacturing to review the issue, understand the failure mode, and to determine the suspect population.
- As of August 04, 2026, FCA US is aware of 0 customer assistance records, 0 warranty claims, 3 field reports, and no other service records potentially relating to this issue for all markets with dates of receipt ranging from May 19, 2026, to May 20, 2026.
- As of August 04, 2026, FCA US is not aware of any accidents or injuries potentially related to this issue for all markets.
- On August 06, 2026, FCA US determined, through the Vehicle Regulations Committee, that a safety defect exists in certain vehicles.

Related NHTSA Recall Number:

Description of Remedy

Remedy Type: Software

Consumer Advisories: ☐ Do Not Drive ☐ Park Outside

Description of remedy program:

FCA US will conduct a voluntary safety recall to reprogram the BCM with updated software.

How remedy component differs from recalled component:

The remedy is to reprogram the BCM with updated software.

Identify how/when recall condition was corrected in production:

Part 573 Safety Recall Report

26V529

Reimbursement Plan

Manufacturer used general reimbursement plan on file.

Recall Schedule

Description of recall schedule:

****08/13/2026:** FCA US will notify dealers on or about 08/20/2026 and begin notifying owners on or about 09/03/2026.

Planned Dealer Notification Date: Aug 20, 2026 - Aug 20, 2026 ☐ No Dealers

Planned Interim Owner Notification Date: ☐ No Owners

Planned Remedy Owner Notification Date: Sep 03, 2026 - Sep 03, 2026 ☐ Phased Recall

Date when VIN will be searchable: Aug 20, 2026