



U.S. Department
of Transportation

National Highway
Traffic Safety
Administration

Part 573 Safety Recall Report

26V634

Manufacturer Name: Airstream, Inc.

Submission Date: Oct 01, 2026

NHTSA Recall No.: 26V634

Manufacturer Recall No.:

Manufacturer Information

Population

Manufacturer Name: Airstream, Inc.

Address: 419 West Pike Street
PO Box 629
Jackson Center OH, 45334-0629

Total number of potentially involved: 91

Estimated percentage with defect: 100%

Vehicle Information

Vehicle 1: 2026-2027 Airstream Rangeline

Product Category: Light Vehicles

Product Type:

Fuel / Propulsion: Compression Ignition Fuel

Production Dates: Aug 29, 2025 - Aug 21, 2026

Number of potentially involved: 91

Descriptive Information:

The recall population was established by reviewing the installation process, and it was determined that the deficiency began occurring due to a change in Production personnel.

Defect / Noncompliance Description

Description of the defect or noncompliance:

On certain MY 2026 and 2027 Rangeline motorhomes, the bond between the vehicle and the fairing may fail, allowing the fairing to separate from the motorhome.

FMVSS1:

FMVSS2:

Description of the safety risk, including crash, fire, death, injury:

If the fairing detaches while the unit is in transit, it could become a projectile, increasing the risk of

Part 573 Safety Recall Report

26V634

personal injury and/or property damage. Airstream is not aware of any crashes or injuries related to this condition.

Description of the cause:

During manufacturing, the mounting surface may have been improperly prepared, resulting in inadequate adhesion of the fairing.

Identification of any warning that can occur:

None

Component Manufacturer

Tier of Supplier:

Supplier Type:

Name:

Address:

Country:

Involved Components

Component Name 1: Fairing

Component Description: Rangeline Poptop Fairing

Component Part Number: 204381-09

Chronology

8/31/2026 – Airstream received information that a Rangeline (Poptop) fairing had detached from a unit in transit.

8/31/2026 – Airstream began an investigation of the fairing separation.

9/2/2026 – Airstream received a second notification of a similar incident involving the Rangeline fairing separation.

9/2/2026 – Airstream requested the unit be returned to the factory for review.

9/21/2026 – Unit arrived at the Airstream factory. A cross-functional review was completed, revealing inadequate surface preparation.

9/24/2026 - The safety committee reviewed all known data and determined a recall is warranted. No warranty claims or injury-related notices regarding this issue have been submitted to Airstream.

Part 573 Safety Recall Report

26V634

Related NHTSA Recall Number:

Description of Remedy

Remedy Type:

Consumer Advisories: ☐ Do Not Drive ☐ Park Outside

Description of remedy program:

We are reviewing our options for the recall remedy and will amend the 573 once the remedy is established.

How remedy component differs from recalled component:

Identify how/when recall condition was corrected in production:

Reimbursement Plan

Manufacturer used general reimbursement plan on file.

Recall Schedule

Description of recall schedule:

Airstream has the utmost urgency in notifying owners about a recall that affects their vehicle. Letters will be sent out once all pertinent information has been gathered.

Planned Dealer Notification Date: Nov 27, 2026 - Nov 27, 2026 ☐ No DealersPlanned Interim Owner Notification Date: Nov 27, 2026 - Nov 27, 2026 ☐ No OwnersPlanned Remedy Owner Notification Date: Nov 27, 2026 - Nov 27, 2026 ☐ Phased Recall

Date when VIN will be searchable: Nov 27, 2026