

[View this email in your browser](#)

IMPORTANT SAFETY RECALL



MODEL Z RECALL

Shore Power inlet lugs REC-2601

1/28/26

Dear <dealer>

It has been decided that units included in the recall population may not have the shore power inlet lugs torqued to proper specifications. This can cause the wires on the back of the inlet to become loose.

We are conducting a Recall Campaign to address this concern for all Model Z units within the following VIN ranges: (Last 6 digits):

011181, 011183 – 011185, 011187, 011188, 011193, 011194, 011197, 011200 – 011216, 011266, 011271, 011273, 011275 – 011280, 011282 – 011284, 011286 – 011287, 011289, 011290, 011295, 011298, 011299, 011307, 011311, 011313, 011359

NOTICE

IT IS A VIOLATION OF FEDERAL LAW FOR A DEALER TO SELL OR LEASE ANY NEW VEHICLES IN DEALER INVENTORY COVERED BY THIS NOTIFICATION UNTIL THE VEHICLE HAS BEEN REPAIRED.

The remedy is to retorque the lugs on the shore power inlet as outlined in the recall field work instructions. This will prevent the wires on the back of the inlet from coming loose.

Brinkley RV will pay for the Campaign to be completed. There is no charge to you for the remedy.

See the Dealer Portal for further details and associated documentation:

1. Sample Retail Owner notification letter

2. Claim Prep & Filing instructions
3. Recall Field Work Instructions
4. NHTSA 573 Safety Recall Report
5. NHTSA Recall Acknowledgement Letter

Relevant information is also being communicated via our Dealer Portal. Retail customers are being contacted through traditional hard copy mailings, e-mail, and social media.

We apologize for any frustration or inconvenience that this situation causes.

Sincerely,

Brinkley Customer Care

Phone: (574) 501-4280

Email: CustomerCare@BrinkleyRV.com

Let's Get Social!



[Why Brinkley RV?](#) | [Model Z](#) | [Model G](#) | [BrinkleyRV.com](#)

Copyright © 2023 Brinkley RV, All rights reserved.

Want to change how you receive these emails?

You can [update your preferences](#) or [unsubscribe from this list](#).