

D095 – PANORAMIC ROOF SIDE FINISHERS

SAFETY RECALL



AFFECTED MODELS	23-26MY Range Rover and Range Rover Sport
VOLUME AFFECTED	178 US 14 CAN
REPAIR	<p>A concern has been identified on certain vehicles where the adhesion process used to re-attach the panoramic roof side finishers during vehicle quality rework operations in the assembly plant may not have been sufficient.</p> <p>An inadequately adhered panoramic roof side finisher could, over time, come partially or completely loose. This could result in distractions to the driver or other road users or, in the event of complete detachment, harm to other road users, particularly pedestrians or two-wheeled vehicles, and increase the risk of injury or a crash. Replacement roof panel moldings will be required.</p>
REPAIR TIME	0.8 hrs + DIDO
CAMPAIGN LAUNCH	Retailers were notified via recall administration bulletin D095ADM1 on March 5th, 2026. The repair bulletin will be published when sufficient replacement parts are available. This is expected by May 19 th , 2026
NOTES	<p>Please review the content in the administration bulletin and follow all instructions relating to unsold vehicles in retailer inventory.</p> <p>Clients will be notified by mail on or before April 17th, 2026.</p>