



**ADMINISTRATION BULLETIN - SAFETY  
RELATED RECALL**

Global Recall  
Action  
Number:  
D095ADM1

Subject:  <b>Panoramic Roof Side Finishers</b>	Publication No.: D095ADM1
	Model: Range Rover (LK)
	Model Year: 2023 - 2026
	Model: Range Rover Sport (L1)
	Model Year: 2023 - 2026
	Date of Issue: 05 March 2026

<b>To:</b>	JLR North America, LLC and JLR Canada ULC.
<b>For the Attention of:</b>	The approved JLR retailer/authorized repairer.

**DESCRIPTION OF ISSUE AND THE EFFECT ON VEHICLE OPERATION**

A concern has been identified on certain Range Rover and Range Rover Sport vehicles where the adhesion process used to re-attach the panoramic roof side finishers during vehicle quality rework operations in the assembly plant may not have been sufficient.

An inadequately adhered panoramic roof side finisher could, over time, come partially or completely loose. This could result in distraction to the driver or other road users or, in the event of complete detachment, harm to other road users, particularly pedestrians or two-wheeled vehicles, and increase the risk of injury or a crash.

**ACTION TO BE TAKEN**

Check the JLR Warranty Portal to make sure affected vehicles are correctly identified prior to starting this campaign. The Warranty Portal will be updated to reflect only those vehicles affected.

Retailers/authorized repairers are required to Quarantine affected new vehicles that are within your control and refrain from releasing the vehicles for new vehicle sale pending completion of the rework action. Affected vehicles already with customers should be updated at the next available opportunity. JLR recommends that affected sales demonstrator and loaner vehicles are repaired before use and that used vehicles are repaired before sale. Retailers/authorized repairers who choose to proceed against this recommendation, where legally permitted, must clearly and conspicuously disclose the open recall to the applicable customers.


**Retailers/authorized repairers are reminded that they must not sell vehicles identified as affected by this campaign until such time as the repair has been successfully completed.**

	<p><b>The following applies to:</b> [NORTH AMERICA]</p>
---	---


**FOR THE ATTENTION OF NORTH AMERICAN TERRITORIES ONLY:**

	<p><b>The following applies to:</b> [NORTH AMERICA]</p>
---	---


National Highway Traffic Safety Administration (NHTSA) reference number: 26V-097.

	<p><b>The following applies to:</b> [NORTH AMERICA]</p>
---	---


Transport Canada (TC) reference number: 2026-074.

	<p><b>The following applies to:</b> [NORTH AMERICA]</p>
---	---

Visit the British Brands Sales Suite (BBSS) website for a list of affected vehicles at your retailer/authorized repairer. Unsold vehicles must be repaired prior to handover of the vehicle for retail sale.

	<p><b>The following applies to:</b> [NORTH AMERICA]</p>
---	---

**REGULATORY INFORMATION**

	<p><b>The following applies to:</b> [NORTH AMERICA]</p>
---	---

JLR North America, LLC and JLR Canada ULC have informed the National Highway Traffic Safety Administration (NHTSA) and Transport Canada (TC) of their intent to perform a Safety Recall on certain 2023 to 2026 Model Year Range Rover and 2023 to

2026 Model Year Range Rover Sport vehicles imported into the United States and Canada markets. Information relating to this Safety Recall will be posted on the NHTSA and TC websites.



**The following applies to:**  
[NORTH AMERICA]

This Safety Recall Administration Bulletin serves as notification to all retailers in the United States and Canada markets that any new affected vehicles may not be sold and delivered for customer use until the Safety Recall repair is completed. Violation of this requirement by a retailer/authorized repairer, in the USA only, could result in a maximum civil penalty of up to the equivalent of \$27,874.00 USD per violation and the equivalent of \$139,356,994.00 USD for a related series of violations.



**The following applies to:**  
[NORTH AMERICA]

#### **OWNER NOTIFICATION**



**The following applies to:**  
[NORTH AMERICA]

Initial owner notification is expected to occur on or before 17th April 2026.

This recall repair procedures and any required parts and/or software are not currently available. This recall repair campaign will be published when all repair procedures and all required parts and/or software are available. This is expected to be completed by TBD.

Yours faithfully

Steve Oldham

Global Customer Care Quality Director