

Update SIB 61 02 26 Recall 26V-115 Replace Left Multifunction Switch has posted

Delivery Stop STOP610032 For Turn Indicator Cancelation

UPDATE 3/13/2016:

SIB 61 02 26 Recall 26V-115: Replace Left Multifunction Switch has been posted in TIS.

A limited number of units are currently in dealer inventory; please review your inventory for affected units, and if any are identified, order the required replacement part. If the switch is not available when ordering, place it on backorder, as parts are being processed into the system and are expected to be available on Monday, March 16, 2026.

Regards

BMW Motorrad USA Technical Aftersales Team