

D113 – DEFENDER 110 3RD ROW SEATBELT MOUNTING STUD – INCORRECT SPECIFICATION SAFETY RECALL



AFFECTED MODELS	26MY Defender 110 equipped with 3rd row seating
VOLUME AFFECTED	582 US 218 CAN
CONCERN	<p>This recall replaces recall D098 for which repairs were suspended on March 25th, 2026.</p> <p>The 3rd row seatbelt outboard lap belt anchorage stud on certain vehicles may not be consistently manufactured to the as-specified ISO strength grade and may not meet JLR's design specification. Vehicles will require modifications to the LH and RH 3rd row seat belt anchor brackets and the addition of 10mm fasteners.</p>
REPAIR TIME	2.4 hrs + DIDO
CAMPAIGN LAUNCH	Retailers were notified via a quarantine bulletin on March 27th, 2026. Repair bulletin was published on March 31st, 2026.
NOTES	<p>D113 supersedes D098. Repairs previously completed prior to the D098 suspension on March 25th, 2026, must have been claimed by April 7th, 2026.</p> <p>The Land Rover supplied parts to complete this repair are currently in transit to the North American Parts Distribution Centers. Parts managers should not place any orders at this time. Separate parts bulletins will be published providing details on how these parts are to be distributed.</p> <p>Retailers must hold from sale, all affected new vehicles in their inventory until the repair is completed. All affected VINs are flagged in TOPIx; the warranty portal and retailer inventory reports are available in BBSS.</p>