

MACK TRUCKS RECALL ALERT



Subject: Non-Compliance Recall SC0493 No Trailer Turn Signal
Recall Number: SC0493
Date: April 7, 2026
Applicable Markets: U.S. Canada Mexico Export

Description

Certain Anthem AN (4) and Mack Pioneer PR (4) models may be equipped with software that does not provide adequate current to support incandescent trailer turn signal indicators. As a result, the subject vehicles do not comply with FMVSS No. 108 S7.1.2 rear turn signal lamps.

If a trailer is operated with inoperative trailer turn signal indicators, vehicles around the trailer would not be able to observe or anticipate when the trailer is turning or changing lanes, which could increase the risk of a crash.

Model and Model Years Affected

Certain MY 2025 – 2027 AN (4) and PR (4) model vehicles manufactured from October 24, 2024 through February 26, 2026.

Vehicle Quantities

97 vehicles (86 US, 11 Canada)

Dealer Responsibilities

The National Traffic and Motor Vehicle Safety Act and Canadian Motor Vehicle Safety Act require dealers to ensure that all new and used vehicles are free of safety defects and comply with all relevant safety standards at the time of delivery to the consumer.

Dealers should make their personnel aware of the safety recall. In the event that a dealer has a vehicle included in the safety recall in their inventory to be sold, the condition must be corrected before releasing it to a customer.

Notification Release Schedule

- Vehicle list will be posted on the Trucks Dealer Portal 4/8/2026.
- Owner notification letters will be released on or before 5/31/2026.
- Repair Instruction will be released once they are available.

Contact

If you have questions or concerns about this recall, contact the Regulatory Affairs Department at vtna.regulatoryaffairs@volvo.com.