

D105 – AUDIO AMPLIFIER FUNCTION CONCERN

UPDATE PRIOR TO SALE



AFFECTED MODELS	26MY Range Rover, Range Rover Sport, and Range Rover Velar
VOLUME AFFECTED	76 US 10 Canada
REPAIR	A concern has been identified where some vehicles may have been manufactured with an Audio Amplifier Module (AAM) that could fail to function correctly due to water damage sustained within the supply chain. If this occurs, there is a potential risk that audible warnings may not sound as intended. The AAM will require replacement and programming.
REPAIR TIME	0.9 hrs – 1.0 hrs + DIDO
CAMPAIGN LAUNCH	April 24th, 2026
NOTES	<p>Retailers are required to hold from sale, all affected vehicles in their inventory until the repair is completed. All affected VINs are flagged in TOPIx, the warranty portal and retailer inventory reports are available in BBSS.</p> <p>As of May 11th, 2026, there are 14 USA and 8 CAN vehicles in unsold retailer inventory. Additional parts are in transit to market.</p>