

SIB 61 05 26 Recall 26V-305: C Evolution Connector Check and Cable Replacement

Hi Dealer Personnel,

SIB 61 05 26 Recall 26V-305: C Evolution Connector Check and Cable Replacement has been posted.

Note: Always check ROSS or Warranty Vehicle Inquiry to confirm whether the repair is available. Even if the SI has been posted, the repair may still be unavailable due to parts supply.

THIS IS NOT A STOP RIDE

You can find the SIB in AWP, AIR WVI, and TIS Motorrad

ABM TIS Motorrad link:

[61 25 26 Recall 26V-305:C Evolution Connector Check and Cable Replacement](#)

Dealer TIS Motorrad link:

[61 05 26 Recall 26V-305: C Evolution Connector Check and Cable Replacement](#)

FAQ:

Q: Is this a High Voltage issue?

A: It depends on the result of the connections check as outlined the repair procedure. Please review and read the bulletin very carefully before performing any checks or repairs.

Q: Who or what type of tech should perform the repair?

A: Because of the motorcycle/scooter model and wiring aspect of the repair, it is highly recommended that a Level 3 tech, with the electrical class and the mandatory required training listed in the Bulletin, performance the check and repair.

Q: What training is required for the repair?

A: Training course "OL19- ME003WBT – C Evolution Maintenance" is **REQUIRED**.

Q: Will there be a repair video?

A: Yes, we are currently in the process of creating a repair video. Once the video is available, it will be on TMSI as required training from that point on.

Q: Is there any special request or procedure that is not usual with other Recalls in the past?

A: Yes, we are requiring a TSARA case for documentation for every repair. Read the Bulletin very carefully before performing any repairs. As the type of case and when a case escalation is needed.

6/22/2026