

Recall Campaign 300: Driver Airbag (DAB) Module Inflator Inspection/Replacement - Remedy Available

Posted Date:
08/05/2026

- 📎 26-01-067H - Driver Airbag (DAB) Module Inflator Inspection and Replacement (RC300) (posted 08.05.26).pdf
- 📎 Recall 300 - DAB Inflator Inspect & Replace - Dealer Notification (Remedy Available) (posted 08.05.26).pdf

Hyundai Motor America (HMA) has launched Remedy Available for Recall 300: Driver Airbag (DAB) Module Inflator Inspection/Replacement.

As required by federal law, dealers must not deliver new vehicles for sale or for lease to customers until all open recalls have been performed. Dealers must perform all open recalls on used vehicles, demo, and rental vehicles prior to placing them into customer use and whenever an affected vehicle is in the shop for any maintenance or repair.

A. Affected Vehicles:

1. VIN Identification: Use the 'Vehicle Information' screen in WebDCS under the 'Campaign Not Performed' section to determine recall applicability.

- a. Certain 2016MY Elantra GT (GD) produced 04/18/2015 – 08/24/2015
 - i. Built by Hyundai Motor Company ("HMC") – VIN starts with "KMH"
- b. Certain 2016MY Elantra (MD) produced 04/21/2015 – 08/21/2015
 - i. Built by HMC – VIN starts with "KMH"
- c. Certain 2015-16MY Elantra (UD) produced 10/14/2014 – 05/13/2015
 - Built by Hyundai Motor Manufacturing Alabama ("HMMA") – VIN starts with "5NP"

B. Recall Description:

Certain Elantra (MD, UD) and Elantra GT (GD) vehicles may be equipped with hybrid airbag inflators that contain propellant outside of density specifications. Lower-density propellant can cause increased internal inflator pressures, potentially leading to rupture of the inflator during airbag deployment. An airbag inflator rupture increases the risk of severe injury or fatality to the driver, passengers, or both.

Technical Service Bulletin (TSB) 26-01-067H provides instructions to inspect and, if necessary, replace the Driver Airbag (DAB) module inflator.

C. Parts Information

1. 1. Driver Air Bag Inflator

- 1. a. Provide an applicable Recall 300 VIN to order the necessary part number.

D. Campaign Documents:

1. 1. TSB 26-01-067H

- 1. a. HyundaiDealer.com > Service > Service Programs > Hyundai Tech Info > Campaign

2. 2. Dealer Notification

- 1. a. HyundaiDealer.com > Service > Service Programs > Hyundai Tech Info > Service News

E. Action Required:

- 1. 1. Confirm VIN eligibility via WebDCS.

2. 2. **Follow TSB 26-01-067H** for the service procedure to inspect the Driver Airbag (DAB) module inflator and if necessary, replace it.
3. 3. **Submit campaign claim** once the service procedure is completed.

We appreciate your continued partnership and commitment to our Hyundai customers.

Thank you for your patience and understanding.

HMA Warranty Campaigns