

GENERAL MOTORS

DCS 7505

URGENT - DISTRIBUTE IMMEDIATELY

Date: May 27, 2026

Subject: REVISION: N262557310-01 – Safety Recall

Roof Rail Airbag Inflator May Rupture

Revised Service Procedure

Models: 2018 Chevrolet Silverado 1500

2019 Chevrolet Silverado 2500/3500

2018 GMC Sierra 1500

2019 GMC Sierra 2500/3500

This bulletin is being revised to include the United States in the deployment/ disposal instructions. Please discard all previous copies of bulletin N262557310.

For dealers with involved vehicles, a listing has been prepared and will be available through GM Global Connect Maxis Field Action Reports or GWM Field Action Batch Search Report. The Inventory tab of the dealer reports will contain VINs that apply to this field action. This information is intended to assist dealers with the **PROMPT COMPLETION** of these vehicles. The Customer In-Service tab will contain customer names and addresses from Motor Vehicle Registration Records. The use of such motor vehicle registration data for any purpose other than follow-up necessary to complete this field action may be a violation of law in several states.

END OF MESSAGE