

DATE: May 22, 2026

TO: All Acura Sales, Service & Parts Managers, and Personnel

FROM: Erik Blank, Manager of Auto Campaigns and Recalls

Re: **EXPANSION**-Stop Sale/Safety Recall: 2017-2026 Multi-Model Seat Weight Sensor Failure

On May 21, 2026, Acura notified NHTSA of a **stop sale** and **safety recall** for approximately 4,800 units of model year 2017-2020 & 2022-2026 MDX, 2019-2024 RDX, and 2018-2021 & 2023 TLX. Affected vehicles may be equipped with seat weight sensors not built to proper specifications. Improperly built sensors could lead to cracking and/or a short circuit of the sensor, resulting in the illumination of the SRS warning light and the passenger airbag indicator remaining OFF. In certain collisions, these seat weight sensors may cause improper deployment of the front passenger airbag, increasing the risk of injury. **Refer to your eResponsibility report or perform an iN VIN status inquiry to determine which units in your inventory are affected.**

REPAIR

Replace the seat weight sensors.

PARTS

Parts will be available at launch. Refer to PIB for details regarding parts availability and ordering.

TOOLS

There are no special tools required for this recall.

SERVICE BULLETINS

The following Service Bulletins have posted to the Service Information System (SIS) as of May 22, 2026. They include repair, parts, and warranty claim information related to this recall.

- 26-013, *Safety Recall: 2018-20 TLX Seat Weight Sensor (DTC U3000-49)*
- 26-014, *Safety Recall: 2021 & 2023 TLX Seat Weight Sensor (DTC U3000-49)*
- 26-015, *Safety Recall: 2022-26 MDX Seat Weight Sensor (DTC U3000-49)*
- 26-016, *Safety Recall: 2017-20 MDX Seat Weight Sensor (DTC U3000-49)*
- 26-017, *Safety Recall: 2019-24 RDX Seat Weight Sensor (DTC U3000-49)*

CLIENT NOTIFICATION

Acura expects to begin initial client notification in early July 2026.

As always, perform an iN VIN status inquiry for all vehicles passing through your dealership to determine eligibility for any open campaigns.