

**Recall 26V-334 (Flat Rate 900012) CAN 2026-252  
Model Z Lippert Curt TCS Shock Bolt Replacement**

**It has been determined that vehicles within the recall population may be equipped with shock retaining bolts on the suspension system that may have been over-torqued, potentially causing the bolt heads to fracture. Under certain operating conditions, if the bolt head fractures while the vehicle is in motion, the bolt head and retaining washer may loosen or detach causing road debris, potentially increasing the risk of vehicle crash. The remedy is to have the TCS shock bolts replaced with new grade 8 bolts, secured with Loctite and torqued to the proper specifications. Brinkley RV will pay for the Campaign to be completed. There is no charge to you for the remedy.**

**This recall affects a total of 6,393 vehicles.**

**Model Z equipped with the Curt TCS suspension system VIN Range (last 6 digits of VIN): 000073 - 013017**

**NOTICE**

**IT IS A VIOLATION OF FEDERAL LAW FOR A DEALER TO SELL OR LEASE ANY  
NEW VEHICLES IN DEALER INVENTORY COVERED BY THIS NOTIFICATION  
UNTIL THE VEHICLE HAS BEEN REPAIRED.**