

[View this email in your browser](#)

IMPORTANT SAFETY RECALL



MODEL Z RECALL

Lippert Curt TCS Shock Bolt Replacement REC - 2602

6/1/26

Dear <dealer>

It has been determined that vehicles within the recall population may be equipped with shock retaining bolts that may have been over-torqued potentially causing the bolt heads to fracture.

We are conducting a Recall Campaign to address this concern for all Model Z units within the following VIN ranges (Last 6 digits) equipped with the Curt TCS suspension:

000073 - 013017

NOTICE

IT IS A VIOLATION OF FEDERAL LAW FOR A DEALER TO SELL OR LEASE ANY NEW VEHICLES IN DEALER INVENTORY COVERED BY THIS NOTIFICATION UNTIL THE VEHICLE HAS BEEN REPAIRED.

The remedy involves removing the existing shock retaining bolts and replacing them with grade 8 – 3/8 -16 x 3/4” bolts. Blue Loctite or an equivalent thread locking compound, must be applied, and the bolts must be torqued to 20 – 30 ft lbs.

Brinkley RV will pay for the Campaign to be completed. There is no charge to you for the remedy.

See the Dealer Portal for further details and associated documentation:

1. Sample Retail Owner notification letter

2. Claim Prep & Filing instructions
3. Recall Field Work Instructions
4. NHTSA 573 Safety Recall Report
5. NHTSA Recall Acknowledgement Letter

Relevant information is also being communicated via our Dealer Portal. Retail customers are being contacted through traditional hard copy mailings, e-mail, and social media.

We apologize for any frustration or inconvenience that this situation causes.

Sincerely,

Brinkley Customer Care

Phone: (574) 501-4280

Email: CustomerCare@BrinkleyRV.com

Let's Get Social!



[Why Brinkley RV?](#) | [Model Z](#) | [Model G](#) | [BrinkleyRV.com](#)

Copyright © 2023 Brinkley RV, All rights reserved.

Want to change how you receive these emails?

You can [update your preferences](#) or [unsubscribe from this list](#).