

IMPORTANT SAFETY RECALL



NHTSA Recall 26V-334 (CAN 2026-252)

Claim Preparation & Inspection/Repair Instructions

Please complete a warranty pre-authorization request using the following codes & labor times:

Labor:

Flat Rate Code: 900012

Fault Code: Supplier Component Failure - Other

Time Allowed: 0.8 hours for tandem axle

Additional work, such as broken bolt extraction or tire removal will be handled on a time and materials basis

Parts: Brinkley Parts Number K131212: Lippert Bolt Replacement Kit (PN 2026070484)

- Hex Head Bolts, 3/8"-16 x 3/4" Grade 8 (x16)

- 0.2oz Loctite Blue 242 capsules (x2)+

In some cases, bolts may have a pre-applied threadlocker patch on them instead of needing the liquid threadlocker applied

- Shop tools and supplies (torque wrench ft-lb rated w/ 3/8" drive, 9/16" crowfoot wrench, ratchet with 9/16" Socket)

Pre-Authorization:

All Brinkley RV dealer recalls will require preauthorization approval prior to claim creation. Promptly file preauthorization through our dealer portal using the information above to confirm the correct flat rate is applied.

Claim Filing:

When repair is complete, promptly file a claim through our dealer portal.

Required photos (see Figure 4A in the work instructions):

- Photos of the replaced bolts that have been torqued to the specs set forth in the work instruction.
- If you have any questions, please call our Customer Care Team at (574) 501-4280.