



Service Engineering Operations
Customer Service Division

Ford Motor Company
PO Box 1904
Dearborn, Michigan 48121

October 7, 2026

TO: All U.S. Ford and Lincoln Dealers

SUBJECT: **NEW VEHICLE DEMONSTRATION / DELIVERY HOLD - Advance Notice**
Safety Recall 26S73
Certain 2015 Transit Connect Vehicles
Incorrect Rear View Camera Replacement

REF: **NEW VEHICLE DEMONSTRATION / DELIVERY HOLD**
Safety Recall 25S89 - Supplement #3
Dated: September 17, 2026

AFFECTED VEHICLES (U.S. Population of Affected Vehicles: 504):

Vehicle	Model Year	Assembly Plant	Build Date Range
Transit Connect	2015	Valencia	August 1, 2014 through July 28, 2015

Affected vehicles are identified in OASIS and FSA VIN Lists.

REASON FOR THIS SAFETY RECALL

All affected vehicles were previously repaired using an incorrect, prior-level part number identified in the Safety Recall 25S89 Dealer Bulletin.

Therefore, these vehicles did not receive the correct rear view camera replacement under 25S89, and customers may experience a blank or distorted image on the center display screen when the vehicle is in reverse. A rear view camera that displays a blank or distorted image while in reverse can reduce or distort the driver's view of what is behind the vehicle, increasing the risk of a crash. If the image is lost for 10 seconds, a Diagnostic Trouble Code (DTC) is set, and the customer will receive a message that the rear view camera is unavailable on the center display screen.

SERVICE ACTION

DO NOT DEMONSTRATE OR DELIVER any new in-stock vehicles involved in this safety recall. For new vehicle storage guidelines, refer to EFC13033, Storage Guidelines for New Vehicles.

A complete dealer bulletin, including technical instructions, is expected to be available to dealers in the fourth quarter of 2027 when a remedy is available for this safety recall.

IMPORTANT: Dealers should open a Repair Order (RO) only when a full dealer bulletin is published. Opening an RO against an Awareness or Advance Notice will result in rejection of the associated warranty claim.

NOTE: For vehicles presented that are exhibiting the concern identified for this Program, **and no longer have applicable warranty coverage**, contact the SSSC for further direction.

CUSTOMER HANDLING – Prior to Remedy Available

As needed, inform customers of the reason for this recall and the remedy delay due to the availability of the new part design.

OWNER NOTIFICATION

Owners of record will be notified via first-class mail within sixty days, which may occur before remedy availability including repair instructions have been provided to dealers.

PLEASE NOTE:

Federal law requires dealers to complete this recall service before a new vehicle is delivered to the buyer or lessee. Violation of this requirement by a dealer could result in a civil penalty of up to \$27,168 per vehicle. Correct all vehicles in your new vehicle inventory prior to delivery.

DEALER-OPERATED RENTAL VEHICLES

The Fixing America's Surface Transportation (FAST) Act law effective June 2016 prohibits a rental company from selling, renting or leasing vehicles subject to a safety recall. Please consult your legal counsel for legal advice.

QUESTIONS & ASSISTANCE

For questions and assistance, contact the Special Service Support Center (SSSC) via the SSSC Web Contact Site. The SSSC Web Contact Site can be accessed through the Professional Technician System (PTS) website using the SSSC link listed at the bottom of the OASIS VIN report screen or listed under the SSSC tab.

Customer Service Division