

July 2026

IMPORTANT SAFETY RECALL 26509

NHTSA RECALL NO. 26V382

This notice applies to your vehicle identified on the enclosed card.

Dear International customer,

This notice is sent to you in accordance with the National Traffic and Motor Vehicle Safety Act.

International Motors, LLC* has decided that certain 2026 and 2027 International® HV™ Series trucks built 07/01/2025 thru 04/16/2026 with the following unique configurations (feature codes):

- 4 Channel ABS (0004AZA), Rear Axle 30/30 brake chamber (0004EXU), Walking Beam with Multi-leaf Spring Suspension 46K with 54 in axle spacing (0014UHK), without Trailer Connection 4-wheel (0004619) and Wheelbase of 250 in (635 cm) or longer
- 4 Channel ABS (0004AZA), Rear Axle 30/30 brake chamber (0004EYL), Walking Beam with Multi-leaf Spring Suspension 46K with 54 in axle spacing (0014UHK), without Trailer Connection 4-wheel (0004619) and Wheelbase of 250 in (635 cm) or longer
- 4 Channel ABS with Automatic Traction Control and Stability Control (0004AZS), Rear Axle 30/30 Brake Chamber (0004EXU), Walking Beam with Multi-leaf Spring Suspension 46K with 54 in axle spacing (0014UHK), without Trailer Connection 4-wheel (0004619) and Wheelbase of 226 in (575 cm) or longer

fail to conform to Federal Motor Vehicle Safety Standard No. 121; Air Brake Systems.

REASON FOR THIS RECALL

The suspect vehicles do not conform to Federal Motor Vehicle Safety Standard (FMVSS) No. 121 S5.3.4 brake release timing requirement. Each service brake system shall meet the requirements of S5.3.4.1 (a).

S5.3.4.1 (a) With an initial service brake chamber air pressure of 95 psi, the air pressure in each brake chamber shall, when measured from the first movement of the service brake control, fall to 5 psi in not more than 0.55 seconds.

RISK TO MOTOR VEHICLE SAFETY

Vehicles not meeting the FMVSS No. 121 brake release timing requirement may have a delay in air pressure released from the brake chambers. Brakes that release too slowly could affect braking performance and increase the risk of a crash without prior warning.

performed free of charge and take approximately 30 minutes to complete.

ACTIONS YOU SHOULD TAKEIf you own this vehicle, please schedule an appointment with any authorized repair center to have your vehicle repaired at no cost to you. You can find your nearest dealer by using the dealer locator at <https://www.internationaltrucks.com/dealer-locator> or by calling 1-800-448-7825 or find the nearest Love's center at <https://www.loves.com>. Love's and Speedco locations in Texas and Louisiana cannot perform warranty services.

If you have already paid for repairs prior to this notice that corrected this noncompliance, you may be eligible for reimbursement of certain repair expenses if they occurred 07/01/2025 thru 07/31/2026. Present your original repair paperwork and proof of payment to any International® dealer and your eligibility will be reviewed. You may also submit a claim using the enclosed Request for Reimbursement card.

If you are the lessor of this vehicle, please forward a copy of this notice to the lessee within ten days to comply with federal regulations.

If you do not own this vehicle, please fill out and return mail the enclosed card so that you will not be contacted again about this recall.

IF YOU NEED FURTHER ASSISTANCE

If you believe that International Motors, LLC has failed to remedy the noncompliance without charge or within a reasonable time, please follow the procedure described in the Owner Assistance Guide section in your Owner's Manual or call toll free 1-800-448-7825.

You may also submit a complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Ave, SE, Washington, DC 20590; or call the toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-888-275-9171); or go to <http://www.safercar.gov>.

International Motors, LLC requests your prompt attention and patience regarding the correction of this noncompliance and apologizes for any inconvenience this may cause you.

REMEDY

The remedy involves removing a 5/8-inch air line and installing a 3/4-inch air line and a quick-release valve. The repair will be